PB90-214354

Superfund Emergency Response Actions: A Summary of Federally Funded Removals. Volume 3

(U.S.) Environmental Protection Agency, Washington, DC

Jun 89

U.S. Department of Commerce
National Technical Information Service
NTIS

TECHNICAL REPORT DATA
(Please read Instructions on the reverse before completing)

1. REPORT NO. EPA/540/8-89/005	2.
3. RECIPIENT'S ACCESSION NO. PB90 214354/AS	
4. TITLE AND SUBTITLE SUPERFUND EMERGENCY RESPONSE ACTIONS: A Summary of Federally Funded Removals--Volume 3	5. REPORT DATE June 1989
	6. PERFORMING ORGANIZATION CODE
7. AUTHOR(S)	8. PERFORMING ORGANIZATION REPORT NO.
9. PERFORMING ORGANIZATION NAME AND ADDRESS OFFICE OF SOLID WASTE AND EMERGENCY RESPONSE U.S. ENVIRONMENTAL PROTECTION AGENCY WASHINGTON, DC 20460	10. PROGRAM ELEMENT NO.
	11. CONTRACT/GRANT NO.
12. SPONSORING AGENCY NAME AND ADDRESS Same as above	13. TYPE OF REPORT AND PERIOD COVERED
	14. SPONSORING AGENCY CODE EPA/540/00

15. SUPPLEMENTARY NOTES

16. ABSTRACT Volume III summarizes short-term removal activities completed during the eighth year of the Superfund program. This document is presented as a series of matrices that are organized numerically by Region and alphabetically by State and site name within each Region. It contains the same types of information included in Volume I and II.

EPA intends to continue providing this information in future updates.

Inquiries regarding information contained in this document should be referred to the appropriate EPA Regional office. A list of EPA contacts and a map delineating the States within each Region are provided in this report. In addition, this document includes a listing of sites found in Volumes I and II. These sites are listed alphabetically by State within their respective Regions. In the back of the report, there is also an alphabetical index of all sites in Volumes I, II, and III.

17. KEY WORDS AND DOCUMENT ANALYSIS

a. DESCRIPTORS	b. IDENTIFIERS/OPEN ENDED TERMS	c. COSATI Field/Group

18. DISTRIBUTION STATEMENT RELEASE TO PUBLIC	19. SECURITY CLASS *(This Report)* UNCLASSIFIED	21. NO. OF PAGES 125
	20. SECURITY CLASS *(This page)* UNCLASSIFIED	22. PRICE

United States
Environmental Protection
Agency

Solid Waste and
Emergency Response
(OS-210)

EPA/540/8-89/005
June 1989

PB90-214354

EPA

Superfund Emergency Response Actions

A Summary Of Federally Funded Removals—Volume 3

REPRODUCED BY
U.S. DEPARTMENT OF COMMERCE
NATIONAL TECHNICAL INFORMATION SERVICE
SPRINGFIELD, VA. 22161

EPA/540/8-89/005
June 1989

Superfund
Emergency Response Actions

A Summary of Federally Funded Removals Volume 3

Office of Solid Waste and Emergency Response

NOTICE

This document has been reviewed by the U.S. Environmental Protection Agency and approved for publication. Any trade names or commercial products mentioned are only examples and are not endorsed or recommended by the U.S. Environmental Protection Agency.

SUPERFUND EMERGENCY RESPONSE ACTIONS

Volume III

The Superfund removal program has achieved significant accomplishments in cleaning up hazardous waste sites and responding to environmental emergencies. For this reason, EPA publishes the Superfund Emergency Response Actions summary, which provides the public with valuable information about Superfund removal actions undertaken by EPA . This document is updated annually. Volume III, the second update to the initial document, summarizes the Superfund removal actions undertaken by EPA between October 1987 and September 1988, or Fiscal Year 1988.

Jonathon Z. Cannon
Acting Assistant Administrator
Office of Solid Waste and Emergency Response

TABLE OF CONTENTS

Page No.

Introduction to the Superfund Removal Program 1

User's Guide 6

Regional Removal Summaries 9

Region I 9

Region II 17

Region III 25

Region IV 37

Region V 49

Region VI 57

Region VII 63

Region VIII 69

Region IX 75

Region X 81

Index of Historical Removal Actions 85

THE SUPERFUND REMOVAL PROGRAM

In response to increasing national hazardous waste disposal problems, in 1980 Congress passed the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), commonly known as Superfund. Superfund authorizes the Federal Government to work with State and local governments and private parties to provide responses to accidental releases of hazardous substances and inactive hazardous waste sites.

Superfund cleanups were financed by a $1.6 billion Trust Fund collected over the first five-year period of the program. The Fund was collected through taxes paid by manufacturers, producers, and exporters and importers of oil and designated chemical substances. It can be used to provide both short-term actions and long-term cleanup, with the latter generally undertaken only at inactive waste sites listed on the National Priorities List (NPL). Short-term actions, including emergency responses, occur in response to hazardous substance releases both at sites on the NPL and sites that are not on the NPL (non-NPL sites). During the sixth year of the program, Congress appropriated funds so that short-term actions could continue while the law was being reauthorized.

On October 17, 1986, the Superfund Amendments and Reauthorization Act (SARA) was enacted. SARA reauthorized Superfund for five more years and provided for a Fund of $8.5 billion. The new Superfund raised the limits on removal actions from six months to 12 months and from $1 million to $2 million. These statutory limitations may be exceeded if site conditions meet one of the two CERCLA exemptions. The "emergency" exemption permits a waiver to the limitations if: 1) there is an immediate risk to public health, welfare or the environment, 2) continued response actions are immediately required to prevent, limit or mitigate an emergency or 3) assistance will not otherwise be provided on a timely basis. The second exemption, referred to as the "consistency" exemption, was enacted under the new Superfund law and permits a waiver to the limitations where a continued response action is otherwise appropriate and consistent with remedial action to be taken. In addition, removal actions, to the maximum extent possible, must contribute to the efficient performance of long-term remedial actions.

The National Contingency Plan (NCP) details the responsibilities of 14 Federal agencies and State and local governments for cleaning up releases of hazardous substances and oil spills to all media: land, air, surface water, and groundwater. The lead responsibility for emergencies occurring inland or in inland waters belongs to the U.S. Environmental Protection Agency (EPA). Primary responsibility for addressing accidental releases in or near coastal waters and the Great Lakes rests with the U.S. Coast Guard (USCG). Although other Federal agencies, such as the Federal Emergency Management Agency and the Agency for Toxic Substances and Disease Registry, do not lead Fund-financed actions, they provide assistance as necessary. In addition, special technical assistance teams and cleanup contractors provide significant support to removal actions.

The Superfund removal program, which manages the short-term actions and emergency responses, is characterized by close cooperation among Federal, State, and local government agencies and between government and industry. Approximately 90 percent of all removals, including emergency responses, are conducted by the responsible party (e.g., generator, transporter, or disposer). For the remaining ten percent, EPA either leads the cleanup, with support and assistance from industry, the Coast Guard, other Federal agencies, and State and local agencies, or assists State and local agencies in managing the response. EPA maintains a technical team on call 24 hours a day to respond to emergencies.

Although emergency responses, whether undertaken by EPA or USCG, must be flexible and tailored to the specific needs of each site or release of hazardous substances, some types of response activities are common to many removal actions. Some of these typical activities are noted below:

- Sampling drums, storage tanks, lagoons, surface water, groundwater, and the surrounding soil and air
- Installing security fencing and providing other security measures
- Removing and disposing of containers and contaminated debris

- Excavating contaminated soils and debris and restoring the site

- Pumping out the contaminated liquids from overflowing lagoons

- Collecting contaminants through drainage systems or skimming devices.

Other activities might include provision of alternate water supplies, installation of decontamination devices, and temporary evacuation of, and provision of housing for threatened individuals.

Occasionally unforeseen circumstances, such as adverse weather conditions, vandalism, fire, or explosion arise and a "restart" is necessary. A restart is the initiation of additional removal activities at a site where there has been a previously completed removal. Twenty-five sites included in the original summary required restarts between October 1, 1987 and September 30, 1988. This update describes only the actions undertaken by EPA at these sites during this period.

Potential and actual releases of hazardous substances are extremely variable in size, threat, and location. Superfund is available for all situations meeting CERCLA and NCP criteria no matter how large or small. Actions under the removal program can range from erecting a fence to removing and disposing of thousands of drums.

From October 1, 1987 through September 30, 1988, EPA Regions performed many technologically or logistically complex responses or used state-of-the-art technologies. Some examples of these removal actions are provided below.

- Nyanza Chemical

This removal action targeted a 39'x77'x8' inground concrete vault (or settling basin) which had been abandoned in 1974-1979 (EPA Region I). The vault used to be open to the air and was used as a settling basin for textile dye manufacturing wastes. The vault contained product when it was buried in 1974-1979 under 2-4 feet of fill. Product leached from the vault over the last 10-15 years and contaminated a 5500-6000 square foot area downgradient of the vault. The principal organic contaminants and their concentrations are listed below:

Nitrobenzene: 1200-9400 ppm
1,2,4 trichlorobenzene: 490-7500 ppm.

From 10/05/87 thru 12/12/87 a mobile 20 ton/day rotary kiln incinerator operation processed approximately 600 tons of contaminated soils. This incinerator passed the 99.99% Destruction Removal Efficiency (DRE) requirements, the particulate, and the hydrocholoric acid stack gas limitations.
The chemical sludges in the vault were not incinerated because of their high moisture content. The materials handling required to prepare the wet sludges would have required a large expenditure of funds and would have prohibited a timely completion of the project. Therefore this sludge was stabilized onsite and then shipped to a RCRA approved landfill.

- American Steel Drum

On December 7, 1987, the United States Environmental Protection Agency, Region V, inititated a removal action at the American Steel Drum Site in Bedford, Ohio. The building was decontaminated during a previous removal action and soils surrounding the facility, two incinerators, and sludge in an underflow dam area remained contaminated with a variety of organic and inorganic constituents including polychlorinated byphenyls (PCBs) and lead. These materials posed threats through direct contact, inhalation of airborne contaminants, and off-site migration through storm sewers and surface water.

The removal action involved the excavation and disposal of 3992 tons of soil contaminated with less than 50 ppm PCBs and other organic and inorganic contaminants and one drum of soil containing greater than 50 ppm PCBs at Stet hazardous waste landfill. Additionally, two incinerators were demolished and disposed of at a hazardous waste landfill. A total of 9,850 gallons of contaminated water was generated during soil excavation activities and sent to a treatment facility for disposal. A total of 193 tons of contaminated sludge in an underflow dam area was excavated, solidified and disposed of at a hazardous waste landfill. Post excavation sampling was conducted to determine the effectiveness of the removal. Subsequently, the site was backfilled with a clayey soil. The removal was completed June 10, 1988, at a cost of $1,036,621.

- Mountain Pine Pressure Treating Site

The Mountain Pine Pressure Treating site (EPA Region VI), an inactive wood preserving facility, is located in 96 acres in Plainview, Arkansas. The facility pressure treated structural timber with solutions of pentachlorophenol (PCP) and chromated copper arsenate (CCA). Two distinct plants, Mountain Pine Pressure Treating Company and Plainview Lumber Company, were operated by the same individuals on contiguous property, and are considered one site by EPA.

The site is located near the center of Plainview and surrounded by residences and stores. A drainage ditch originates at the north end of the site and extends southerly across the site into Porter Creek which flows into Lake Nimrod, the water supply for Plainview and surrounding area. The site features included a 1.4 million gallon PCP recovery pond, wastewater evaporation pond (2 million gallon capacity), the older PCP plant, the CCA plant and CCA containments and sump.

The treating fluid and water from the pressure chambers were drained into the recovery pond where the treating fluid was recovered. Excess water was pumped from the PCP pond to the evaporation pond and recycled through a spray evaporator.

Approximately 8,000 gallons of PCP treating fluid was contained in several tanks in the PCP plant. Thirty-five sacks of raw PCP were found inside the plant structure. The soil in the immediate plant area was saturated with the oily PCP fluid.

The CCA plant had three tanks of spent CCA treating fluid. The tanks had a secondary containment which was filled with accumulated contaminated rainwater. A containment surrounded the CCA pressure treating chamber and was connected to a sump inside the plant structure. The total volume of accumulated rainwater in the containments and sumps was approximately 80, 000 gallons.

On November 20, 1987, EPA's Emergency Response Branch (ERB) was notified of the potential threat from the overfilled PCP recovery pond. On November 27, 1987, a site assessment was performed and confirmed that the pond had overflowed into the drainage ditch. The primary threats posed were direct contact hazards and surface run-off of contaminants from the PCP recovery pond. Lab analysis showed a PCP concentration of 1.89 parts per million (ppm) and arsenic concentration of 3.4 ppm in the pond water. A layer of oil floating on the top had a PCP concentration of 1200 ppm. Only 2 inches of freeboard remained and the water pressure threatened the integrity of the earthen dikes.

The evaporation pond had approximately 3 feet of freeboard and analysis showed nondetectable levels of PCP and 0.778 parts per billion (ppb) of arsenic.

The tanks in the PCP plant contained treating fluids with concentration of PCP up to 7 percent. The soils in and around the plant had PCP concentrations up to 3700 ppm, and were saturated with the treating fluid.

The CCA plant containments and sump had arsenic concentrations of 8 ppm. No freeboard was available in the containments and they had overflowed. The tanks contained spent CCA treating fluids with copper, chromium and arsenic concentrations of 5 to 10 percent.

The Regional Administrator granted verbal approval on December 10, 1987 for an Emergency Response Clean-up, and EPA/ERB mobilized and began the action the next day.

The oil layer was skimmed off the PCP Recovery Pond using booms and secured in drums. The water was treated by spraying alum and ferric sulfate flocculents into the water to precipitate the metals. The metals precipitated out into the sludge and reduced the concentrations of arsenic, copper and chromium to a level which met the discharge standards established by the Arkansas Department of Pollution Control and Ecology (ADPC&E). The pond water was pumped through sand filter/carbon absorption units to remove the PCP. The effluent was discharged into a holding pond until sample analysis confirmed the PCP removal.

During the pumpdown, the PCP recovery pond water required a second application of the flocculents due to the metals resolubilizing. Water from the CCA plant containments and sump was transferred and treated at that

time. Based on flowrates, 1,415,550 gallons of water from the pond and 80,000 gallons from the CCA plant were treated and released through the carbon units.

After the water was removed from the PCP recovery pond, the sludge was solidified. Kiln dust and rice hulls were used to solidify approximately 6,000 cubic yards of sludge. The oil which had been skimmed off the pond was solidified and added to the sludge. The solidified sludge was compacted into the north end of the pond and capped with visqueen and 2 to 3 feet of barrowed clay. The capped area was brought to a stable grade and revegetated.

The treating fluids from the tanks in the PCP plant were added to the sludge from the PCP recovery pond, and solidified with kiln dust and rice hulls. The saturated soils were removed from the plant area, and combined with the solidified sludge. The area was capped with 2 to 3 feet of clean clay.

The sacks of raw PCP contained dioxin concentrations up to 6.93 ppm. The dioxin concentration did not allow for off-site disposal. The sacks and pallet were placed inside one of the pressure chambers and sealed and posted with warning signs.

The contaminated water from the CCA Plant tanks, containments and sump was transferred to the PCP recovery pond. The water was then retreated and released.

Efforts were made to treat the tank fluids similarly to the pond waters, but the small size and weak bonding of the particulate and large surface area relative to the volume hampered the effectiveness of the process. Flocculation treatments yielded a reduced arsenic concentration of 30 ppb, but when the water was transferred the arsenic resolubilized to above the 50 ppb release criteria. The metals were put back in solution, and the fluids were transported to Disposal Systems, Inc. for deepwell injection.

As a result of the action, 4,011,550 gallons of contaminated water were treated and released; 6,000 cubic yards of sludge and 5,000 cubic yards of contaminated soil were solidified and capped; and 30,000 gallons of CCA treating fluid were disposed of by off-site deepwell injection. The immediate threat from the overflow of the PCP recovery pond was eliminated by the treatment of the water, and closing of the pond. The imminent and substantial threats of direct contact, and the migration of contaminants into the Lake Nimrod waters were mitigated by the actions taken on the evaporation pond, saturated soils, and CCA fluids. The action was completed on April 16, 1988.

- Baldwin Park

This site (EPA Region VII) is a 170-acre tract of land on which the Northeastern Pharmaceutical and Chemical Company dumped filter cake wastes from their hexachlorophene process. High concentrations of dioxin were discovered near a trench and in a dump on site.

The two contaminated areas were fenced and the earth was excavated, guided by new dioxin levels established by Region VII and the Agency for Toxic Substance and Disease Registry (ATSDR). ATSDR is a Federal agency that studies and monitors illnesses caused by toxic substances. Between 150 and 200 cubic yards of soil with over 20 parts per billion concentration of dioxin were transported to a mobile incinerator established at another site, named Denney Farm.

The Denney Farm incinerator is the only facility in history that has been licensed to treat dioxin. A high temperature rotary kiln incinerator, the unit converts dioxin tainted soil into water, carbon dioxide, and ash that has only minimal levels of dioxin. The treated ash was tested and then disposed of in a landfill.

The excavated sites at Baldwin Park were capped to contain the remaining low level contaminated soil and seeded to establish a cover of vegetation. The cost of this removal action, not including incineration, was $140,000.

- Poly-Carb Incorporated

On May 27, 1985 between 7200 and 9000 gallons of a phenol and cresol solution spilled from a holding tank at Poly-Carb Inc., a former waste conversion facility located in Wells, Nevada (EPA Region IX). Roughly 300 cubic yards of soil were contaminated. A serious threat was posed to groundwater primarily because of the shallow aquifer underlying the site. The Town of Wells relies entirely on groundwater for its water supply. Both

municipal wells were approximately two miles downgradient from the site. Operations were recently abandoned, and the risk of exposure to the public and grazing livestock was also a concern.

To devise the best approach for on-site treatment, EPA's Environmental Response Team performed several treatability studies. Three innovative treatment methods were tested: passive evaporation, soil washing, and biological degradation. Due to high temperatues and dry and windy weather conditions, the treatment chosen was a combination of the passive evaporation and soil washing methods. This dual treatment procedure proved to be both innovative and cost effective.

Treatment began in June 1987. Contaminants were washed out of the soil in a lined treatment area and removed with activated carbon. Wells were installed to serve the dual function of groundwater monitoring and water supply for the treatment area. Soil and water samples were collected periodically to monitor the operation of the system. Initial samples indicated phenol and cresol levels at 2300 ppm and 1480 ppm, respectively.

In Aug. 1988, EPA terminated and dismantled the treatment system after contaminants had been effectively reduced to below 1 ppm. A total of thirty drums of contaminated carbon were transported to Rollins Environmental Services, Inc., Deer Park, Texas for thermal treatment and incineration. The final cost of the removal was $475,000.

From Dec.1980 through Sept. 1987, EPA completed 776 removal actions at a cost of $156,892,190. From Oct. 1987 through Sept. 1988, EPA completed 219 removal actions, more than in any other single year of the Superfund program. An additional $91 million was spent on FY 88 removal actions that were completed. Total Superfund removal completions and associated costs for the period 12/11/80 to 09/30/88 are as follows:

TOTAL COMPLETIONS

NPL* SITES	192
NON-NPL SITES	803
TOTAL	995

TOTAL COSTS

NPL* SITES	$90,779,443
NON-NPL SITES	$158,250,654
TOTAL**	$249,030,097

* National Priorities List (NPL) - List of nationwide priority hazardous waste sites requiring comprehensive, long-time actions under Superfund.

** Does not include funds for sites where removal activities were ongoing as of 09/30/88.

USER'S GUIDE

Volume III summarizes short-term removal activities completed during the eighth year of the Superfund program. This document is presented as a series of matrices that are organized numerically by Region and alphabetically by State and site name within each Region. It contains the same types of information included in Volume I and II.

EPA intends to continue providing this information in future updates.

Inquiries regarding information contained in this document should be referred to the appropriate EPA Regional office. A list of EPA contacts and a map delineating the States within each Region are provided in this report. In addition, this document includes a listing of sites found in Volumes I and II. These sites are listed alphabetically by State within their respective Regions. In the back of the report, there is also an alphabetical index of all sites in Volumes I, II, and III.

Much of the work EPA and the USCG undertake in response to releases of hazardous substances is highly technical. Definitions of the information provided in the matrices that follow are presented below.

Key to FY88 Superfund Emergency Response Actions Data

1. REGION: EPA Regions 01, 02, 03, 04, 05, 06, 07, 08, 09, 10

2. NAME/LOCATION: Site name and local jurisdiction

3. STATE: Standard State abbreviation

4. NPL STATUS: (Y) Yes - on proposed or final NPL when action started
   (N) No - not on proposed or final NPL when action started

5. COST: These are extramural costs, which include cleanup contractor costs.

6. Start and Completion Dates

7. INCIDENT CATEGORY:

- Active Production Facility - any ongoing operation which manufactures, recycles, handles, stores or transports hazardous materials or waste as a primary ingredient, product or by-product of operations, or any location contaminated due to off-site migration of hazardous materials or wastes from such ongoing operations.

- Inactive Production Facility - any facility no longer in operation which manufactured, recycled, handled, stored or transported hazardous materials or wastes as a primary ingredient, product or by-product of operations, or any location contaminated due to off-site migration of hazardous materials or wastes from such previous operations.

- Active Waste Management Facility - any ongoing legal or illegal operation or site whose primary purpose is to handle, exchange, transfer, store, treat or dispose of hazardous materials or wastes, or any location contaminated due to off-site migration of hazardous materials or wastes from such a facility or site.

- Inactive Waste Management Facility - any former legal or illegal operation or site whose primary purpose was to handle, exchange, transfer, store, treat or dispose of hazardous materials or wastes, or any location contaminated due to off-site migration of hazardous materials or wastes from such a facility or site.

- Midnight Dump - any illegal dumping of hazardous substances into the air, land or water or other element, whether accidental or deliberate.

- Transportation-Related - any release or potential release of hazardous substances due to a transportation situation, accident or malfunction.

- Other - any release of hazardous substances which do not conform to any of the above categories and/or where sources of contamination are unknown.

8. DESCRIPTION: A brief account of site events or conditions necessitating a response action.

9. PRIMARY CONTAMINANTS CATEGORY:

- Dioxin
- PCBs
- Asbestos
- Cyanide
- Volatile Organics
- Non-volatile Organics
- Pesticides
- Waste Oils
- Toxic Gases
- Metals
- Acids
- Bases
- Solvents
- Low-level Radioactive Waste
- Naturally Occurring Radioactive Waste
- Non-hazardous Materials

10. THREAT CATEGORY:

- Air contamination
- Direct contact - skin contact, ingestion, inhalation
- Drinking water contamination
- Ecological damage
- Fire/explosion hazard
- Food chain contamination
- Groundwater contamination
- Soil contamination
- Surface water contamination

11. MITIGATIVE ACTIONS:

- Migration control - specific measures used to control or eliminate contaminants from migrating off site
- Provision of alternate water supplies - temporary or permanent
- Temporary relocation/evacuation - of nearby populations
- Controlling source of threat
  - securing containers: sealing open containers and putting leaky, corroded containers of hazardous substances into new containers
  - reducing volume of hazardous substances in lagoons/containment areas
  - isolating incompatible substances
  - covering/capping: containment of airborne threats, landfills, lagoons, hazardous materials
  - extinguishing a fire
  - bulking materials
  - solidifying materials
  - neutralizing materials
  - collecting and/or retaining contaminants
  - other (specify).
- Excavation - soil, contaminated materials, containers
- Site restoration - backfilling, grading, seeding, repaving
- Treatment/disposal of wastes - all treatment/disposal done in accordance with applicable hazardous waste management regulations
- Alternative technology indicators - alternatives to land disposal that may be used to treat or dispose of wastes in accordance with applicable hazardous waste management regulations:
  - Recycling - treats or processes hazardous waste to recapture material that may be reused in manufacturing and other processes
  - Thermal Destruction, e.g., incineration - destroys or reduces waste to a safer concentration through heat application
  - Stabilization, e.g., cement-based techniques - treatment method that limits solubility or toxicity of hazardous waste constituents
  - Chemical, e.g., chemical oxidation - addition of chemical compounds to hazardous waste to destroy or neutralize hazardous waste constituents

- Physical - Phase Separation, e.g., gravity separation - physical process whereby solids or oil are removed from liquid

- Physical - Component Separation, e.g., air stripping - physiochemical process involving ionic separation or separating dissolved solids from liquid

- Biological, e.g., activated sludge - uses microorganisms to degrade organic compounds

U.S. EPA REGION 1

For Information Contact:

Chief, Emergency Planning and Response Branch,
Environmental Services Division
60 Westview Street
Lexington, MA 02173
(617) 860-4300

REGION I COMPLETIONS LISTED IN VOLUMES I AND II

CONNECTICUT
Bourdeaudhui
Connecticut River Drum
Housatonic River Drums
Kapinos Site
Linemaster Switch Corp.
O'Sullivan's Island Drum
Rye Street Pesticide

MAINE
Androscoggin Rivers
Great Diamond Island - CG
Kennebec (flood)
Keswick Road - CG
Pinette's Salvage Yard
Saco Tannery Waste Pits
Union Chemical Co., Inc.

MASSACHUSETTS
Abandoned Drum - CG
Baird & McGuire
Beal Street Drum
Breakneck Road
Cannon Engineering Corp. (CEC)
Charles George Reclamation Landfill
Dean Street (Norwood PCBs)
High Sachem
Hougels Neck - CG
Industrial Avenue (Lowell)
Industri-Plex
Iron Horse Park
Midnight Dump
Nanpasket Beach - CG
New Bedford Site - CG
Silresim Chemical Corp.

NEW HAMPSHIRE
Auburn Road
Burns Hill Road
Bursey Asbestos
Gonic Sites
Hall Street
Johns Manville Asbestos Site
Keefe Environmental Services
Lake Sunapee
Lowell Road
Matarazzo
Mottolo Pig Farm
Ottati & Goss/Kingston Steel Drum
Pointer Asbestos
Ridge Ave. Asbestos
S Bank Asbestos
Savage Municipal Water Supply
Shady Lane Asbestos
Sylvester
Tinkham Garage

RHODE ISLAND
Castle Hill - CG
Cooks Landfill
Davis Liquid Waste
Picillo Farm
Stamina Mills, Inc.
Western Sand & Gravel

VERMONT
Cyanide Treatment
Old Springfield Landfill Site
Pine Street Canal

REGION 1

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Rolfite Canal Street Site **City** Shelton **State** CT **NPL** N **Cost** $1,774,800 **Start Date** 06/29/87 **Completion Date** 03/17/88	Active Production Facility Numerous organic and inorganic liquids and solids were improperly stored in approximately 800 55-gallon drums, underground vaults, above-ground tanks and reaction vessels. Many of these containers were deteriorated and leaking.	Volatile Organics Non-volatile Organics Pesticides Metals Solvents	Direct Contact Fire/Explosion Hazard	Site Security Sampling/Analysis Organized Materials Overpacked Drums Pumped Contaminants Site Restoration Disposal
Name Cannon Engineering Corporation **City** Bridgewater **State** MA **NPL** Y **Cost** $645,000 **Start Date** 08/10/87 **Completion Date** 01/23/88	Inactive Waste Management Facility Laboratory chemicals and approximately 100 samples of unknown materials posed a significant threat of fire and explosion. Other sources of danger included hundreds of five-gallon pails of paints and paint removers, two tank trailers and approximately twenty drums of unknown material, all deteriorating to some degree.	Cyanide Acids Volatile Organics Solvents	Fire/Explosion Hazard	Site Security Organized Materials Sampling/Analysis Bulked Materials Disposal
Name Cape Cod Canal (CG) **City** Sandwich **State** MA **NPL** N **Cost** $185,253 **Start Date** 12/03/87 **Completion Date** 12/09/87	Other A barge with containers came loose from a tug, threatening a chemical spill.	Volatile Organics	Surface Water Contamination	Sampling/Analysis
Name Chatham Beach (CG) **City** Chatham **State** MA **NPL** N **Cost** $3,100 **Start Date** 08/10/88 **Completion Date** 09/27/88	Other Abandoned drums washed ashore on the beach.	Waste Oils	Surface Water Contamination	Sampling/Analysis Disposal

+ Note: Previous removal was completed at site. See Introduction for details.

REGION 1

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name #7 Commercial Street **City** Brockton **State** MA **NPL** N **Cost** $25,000 **Start Date** 02/17/88 **Completion Date** 02/24/88	Midnight Dump A container labelled "caution infectious wastes" and a sealed package of medical suppies were discovered in a recovered stolen van.	Infectious Wastes	Air Contamination/Inhalation Direct Contact	Sampling/Analysis Overpacked Drums AT: Thermal Destruction
Name Cottage Street **City** Dorchester **State** MA **NPL** N **Cost** $2,500 **Start Date** 08/12/88 **Completion Date** 08/12/88	Midnight Dump There was a midnight dump by an unknown source.	Unknown	Direct Contact	Overpacked Drums Disposal
Name Fairview Road **City** Norwood **State** MA **NPL** N **Cost** $2,500 **Start Date** 05/19/88 **Completion Date** 05/19/88	Midnight Dump Drums were abandoned along a roadside.	Unknown	Direct Contact	Sampling/Analysis Disposal
Name Industri-Plex + **City** Woburn **State** MA **NPL** Y **Cost** $40,000 **Start Date** 05/11/88 **Completion Date** 06/18/88	Inactive Production Facility Wastes from a chemical plant and glue factory were buried on the 244-acre property in an industrial park. The original fence was vandalized.	Metals	Direct Contact Groundwater Contamination Soil Contamination	Site Security
Name Lowney Way **City** Charleston **State** MA **NPL** N **Cost** $2,500 **Start Date** 03/09/88 **Completion Date** 03/10/88	Midnight Dump A two to three pound plastic bag of asbestos labelled "asbestos waste" was discovered in a densely populated urban area where adults and children had easy access to the substance.	Asbestos	Air Contamination/Inhalation Direct Contact	Overpacked Drums Disposal

+ Note: Previous removal was completed at site. See Introduction for details.

REGION 1

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Nantasket Beach **City** Hull **State** MA **NPL** N **Cost** $2,000 **Start Date** 04/26/88 **Completion Date** 04/27/88	Midnight Dump A compressed gas cylinder releasing a green substance washed ashore on Nantasket Beach.	Volatile Organics	Air Contamination/Inhalation	Sampling/Analysis Overpacked Materials Disposal
Name Nyanza Chemical **City** Ashland **State** MA **NPL** Y **Cost** $2,243,000 **Start Date** 05/11/87 **Completion Date** 06/10/88	Active Production Facility An abandoned underground vault containing chemical sludges from a dye manufacturing process leaked sludges and chemicals into soils downgradient of the vault.	Volatile Organics Pesticides Metals Solvents	Air Contamination/Inhalation Direct Contact Groundwater Contamination Surface Water Contamination	Sampling/Analysis Built Road Relocated Treatment System Excavation Solidified Materials Neutralized Materials Disposal Site Restoration
Name Salem Acres **City** Salem **State** MA **NPL** Y **Cost** $1,472,000 **Start Date** 04/10/87 **Completion Date** 04/08/88	Inactive Waste Management Facility Following four days of severe rains, two of several lagoons near a residential area oveflowed into Strongwater Brook and adjacent wetland. These lagoons held sanitary sewerage, and grit and grease sludges buried between 1947 and 1969.	PCBs Metals	Direct Contact Surface Water Contamination	Site Security Sampling/Analysis Containment/Retention Migration Control Solidified Materials Pumped Contaminants Excavation Capping Site Restoration Disposal
Name Samoset Avenue Chemical Spill **City** Hull **State** MA **NPL** N **Cost** $3,000 **Start Date** 10/02/87 **Completion Date** 10/03/87	Midnight Dump Approximately five gallons of a very caustic substance were dumped on a sidewalk. The site was located in a heavily populated residential area two blocks from the shore of the Massachusetts Bay.	Unknown Caustic Substance	Direct Contact Soil Contamination Surface Water Contamination	Sampling/Analysis Excavation Solidified Materials Organized Materials Disposal

+ Note: Previous removal was completed at site. See Introduction for details.

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Niquette Dr. Asbestos Area 1 **City** Nashua **State** NH **NPL** N **Cost** $250,000 **Start Date** 05/15/87 **Completion Date** 10/24/87	Other Asbestos baghouse and pellet wastes were exposed throughout the backyards of three adjacent residential properties located in a wetland area.	Asbestos	Direct Contact	Sampling/Analysis Excavation Capping Site Restorartion Disposal
Name Niquette Dr. Asbestos Area 2 **City** Nashua **State** NH **NPL** N **Cost** $250,000 **Start Date** 05/15/87 **Completion Date** 10/24/87	Other Exposed asbestos was located in an unrestricted swampy area along Salmon Brook.	Asbestos	Direct Contact	Sampling/Analysis Excavation Capping Site Restoration Disposal
Name Russell Avenue Asbestos Area **City** Nashua **State** NH **NPL** N **Cost** $450,000 **Start Date** 04/01/87 **Completion Date** 10/07/87	Other Large areas of exposed asbestos were on three acres bordered by residential properties and Salmon Brook. A steep embankment on the southern and western boundaries leveled off to a marshy area at Salmon Brook.	Asbestos	Air Contamination/Inhalation	Sampling/Analysis Capping Disposal
Name Tibbetts Road + **City** Barrington **State** NH **NPL** Y **Cost** $2,070,011 **Start Date** 09/30/85 **Completion Date** 03/30/88	Inactive Waste Management Facility Volatile organic compounds from 350 deteriorated and leaking drums contaminated shallow wells serving private residences within 50 yards of the site. PCB-and dioxin-contaminated soil were onsite.	Dioxin PCBs Volatile Organics Solvents	Direct Contact Fire/Explosion Hazard Groundwater Contamination Soil Contamination Surface Water Contamination	Sampling/Analysis Excavation Neutralized Materials Monitored Wells Pumped Contaminants Provided Bottled Water Constructed Water Main Disposal AT: Thermal Destruction

+ Note: Previous removal was completed at site. See Introduction for details.

REGION 1

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Tibbetts Road + **City** Barrington **State** NH **NPL** Y **Cost** $2,070,011 **Start Date** 07/20/88 **Completion Date** 08/26/88	Other Volatile organic compounds from 350 deteriorated and leaking drums contaminated shallow wells serving private residences within 50 yards of the site. PCB-and dioxin-contaminated soil were onsite.	Dioxin PCBs Volatile Organics Solvents Pesticides	Direct Contact Fire/Explosion Hazard Groundwater Contamination Soil Contamination Surface Water Contamination	Constructed Water Main Provided Hookups to Water Main Installed Water Treatment Plant
Name Stamina Mills + **City** North Smithfield **State** RI **NPL** Y **Cost** $150,000 **Start Date** 08/08/88 **Completion Date** 08/17/88	Inactive Production Facility Drinking water wells near a textile company were contaminated with Trichloroethylene (TCE). During the early 1970s, 200 gallons of TCE were spilled at this textile company. A 1977 fire destroyed the mill and caused the release of 600-700 gallons of TCE. Still bottoms from the mills solvent recovery system were landfilled on site.	Solvents	Drinking Water Contamination Groundwater Contamination	Removal of Leaking Storage Tanks

+ Note: Previous removal was completed at site. See Introduction for details.

U. S. EPA REGION 2

For Information Contact:

Chief, Response and Prevention Branch, Emergency and Remedial Response Division
Woodbridge Avenue
Raritan Depot-Bldg. 209
Edison, NJ 08837
(201) 321-6657

REGION II COMPLETIONS LISTED IN VOLUMES I AND II

NEW JERSEY
Beach Contamination
Blue Poly Drum - CG
Brady Metals
Burnt Fly Bog
Camplain Road
Chemical Leaman Tanklines
Delancy Trailer
Chemical Control
Delaware River - CG
Duane Marine
Fried Industries
Gems Landfill
Goose Farm
Hayes Park Pool
Hillsborough-Route 206
Horseshoe Road Dump
Kearny Drum Dump #1 & #5
Kearny Drum Dump #2
Kin-Buc Landfill
Lipari Landfill
Lockwood Street
Minsei
Myers Property
Perona Tire Fire
Pomona Oaks Residential Wells
Quanta Resources
Renora, Inc.
Signo Delta Warehouse
Waldick Aerospace Devices

NEW YORK
Abandoned Drums
Abandoned Drum- Erie Canal - CG
American Thermostat
Asbestos Dumping
Asbestos/Torry Place
Bayshore
Berncolor Inc. - CG
Blooming Grove
Byron Barrel & Drum
Cayadutta Creek
Fort Drum
Fort Totten - CG
Fulton Terminals
Gazzola Drive
Hyde Park Drum
Jagger Lane
Kentucky Avenue Well Field
Linclon Avenue
Long Island Beach - CG
Love Canal (Black Creek)
Madison Wire Co.
Mek Spill
Moreland Site
N. Lindenhurst
Olean Well Field
Parthey Lane
Pollution Abatement Services (PAS)
Primo Shield
Sag Harbor
Sammis Avenue - Deer Park
Shirley #2
Signo/Coty
Signo/Kenston
Signo Trading

NEW YORK (Cont.)
Town of Kent
Wading River
Wallkill Well
Wide Beach Development
Windus Drive
York Oil Company

PUERTO RICO
Camuy River Dump
Dorado Drum Site
Puerto Rico Organic Inc.

REGION 2

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Atlantic Resources **City** Sayerville **State** NJ **NPL** N **Cost** $669,000 **Start Date** 02/05/87 **Completion Date** 07/28/88	Inactive Production Facility Vats, drums of acids, containers of unknowns, two labs and eight incinerators were located on the site of an abandoned precious metal recovery facility. Soil contaminated with 2, 3, 7, 8 TCDD had been identified near the incinerators and a chronic discharge of oil was flowing into the nearby Raritan River.	Dioxin PCBs Pesticides Waste Oils Metals Acids Solvents	Direct Contact Fire/Explosion Hazard Surface Water Contamination	Site Security Sampling/Analysis Containment/Retention Excavation Overpacked Drums Bulked Materials Organized Materials Pumped Contaminants Disposal AT: Thermal Destruction
Name Chemical Insecticide Corp. **City** Edison Twp **State** NJ **NPL** N **Cost** $15,900 **Start Date** 02/16/88 **Completion Date** 02/26/88	Inactive Production Facility A company produced pesticides and herbicides until declaring bankruptcy.	Dioxin Pesticides	Direct Contact Groundwater Contamination	Sampling/Analysis Site Security
Name Colter St. **City** Toms River **State** NJ **NPL** N **Cost** $1,800 **Start Date** 03/08/88 **Completion Date** 08/24/88	Other Private drinking supplies exceeded the removal action level for mercury.	Metals	Drinking Water Contamination Groundwater Contamination	Sampling/Analysis Provided Bottled Water Provided Hookups to Water Main
Name Cooper River (CG) **City** Camden **State** NJ **NPL** N **Cost** $5,000 **Start Date** 02/17/88 **Completion Date** 02/21/88	Other A spill occurred on the Cooper River. The dark brown substance was a sheen and smelled like paint.	Waste Oils	Surface Water Contamination	Sampling/Analysis

+Note: Previous removal was completed at site. See Introduction for details.

REGION 2

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name East Hanover Site **City** East Hanover **State** NJ **NPL** N **Cost** $23,000 **Start Date** 04/22/88 **Completion Date** 07/15/88	Other Private water supplies exceeded the removal action level for volatile organics.	Volatile Organics Solvents	Drinking Water Contamination Groundwater Contamination	Sampling/Analysis Provided Bottled Water Water Line Connection Provided Hookups to Water Main Site Restoration
Name East Hanover Site + **City** East Hanover **State** NJ **NPL** N **Cost** $0 **Start Date** 09/10/88 **Completion Date** 09/30/88	Other Following a previous action, one private residential water supply remained that exceeded the removal action level for volatile organics.	Volatile Organics Solvents	Drinking Water Contamination Groundwater Contamination	Provided Hookups to Water Main
Name Industrial Latex **City** Wallington **State** NJ **NPL** Y **Cost** $1,412,000 **Start Date** 04/09/87 **Completion Date** 10/02/87	Inactive Production Facility An inactive 9.67-acre adhesives/rubber manufacturing facility was located in a dense residential/commercial area; 10,000 people lived within 0.5 mile of the site. Two main buildings contained numerous containers of hazardous substances. Extensive fires and vandalism had occurred at this unrestricted site.	PCBs Solvents	Air Contamination/Inhalation Direct Contact Fire/Explosion Hazard Groundwater Contamination Surface Water Contamination	Site Security Sampling/Analysis Excavation Organized Materials Air/Meterological Monitoring Pumped Contaminants Neutralized Materials Disposal AT: Thermal Destruction
Name International Metallurgical Service **City** Newark **State** NJ **NPL** N **Cost** $460,000 **Start Date** 02/22/88 **Completion Date** 07/11/88	Inactive Production Facility Four-hundred and fifty lab containers, 45 tanks, and 100 drums were contained in an abandoned precious metals recovery facility, which had been subjected to vandalism.	Cyanide Volatile Organics Metals Acids Bases	Air Contamination/Inhalation Fire/Explosion Hazard Food Chain Contamination	Site Security Sampling/Analysis Organized Materials Overpacked Drums Air Monitoring AT: Thermal Destruction

+Note: Previous removal was completed at site. See Introduction for details.

REGION 2

Superfund Emergency Response Actions

Site Information		Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name	Myers Prop.+	Inactive Production Facility Pesticides, herbicides and paint stored in an old barn had contaminated one well used for drinking water.	Asbestos Volatile Organics Pesticides Metals Solvents	Direct Contact Drinking Water Contamination Groundwater Contamination Surface Water Contamination	Site Security Sampling/Analysis Migration Control
City	Franklin Twp				
State	NJ				
NPL	Y				
Cost	$39,000				
Start Date	10/28/87				
Completion Date	03/12/88				
Name	Nascolite Corp	Inactive Production Facility Polymethyl methacrylate was manufactured for 27 years on this 17.5-acre site located in a wooded area. Underground tanks holding the plant's residue leaked, causing soil and groundwater contamination.	Asbestos Volatile Organics Metals Solvents	Direct Contact Fire/Explosion Hazard Groundwater Contamination Soil Contamination	Extinguished Fire Excavation Pumped Contaminants Bulked Materials Overpacked Drums Organized Materials Disposal
City	Millville				
State	NJ				
NPL	Y				
Cost	$195,500				
Start Date	10/28/87				
Completion Date	03/21/88				
Name	Pulverizing Services	Inactive Production Facility Pesticides and chemicals stored at the defunct facility posed a significant threat to a large area of the township.	Pesticides	Air Contamination/Inhalation Direct Contact Fire/Explosion Hazard Soil Contamination Groundwater Contamination Drinking Water Contamination	Site Security Sampling/Analysis Organized Materials Disposal
City	Moorestown				
State	NJ				
NPL	N				
Cost	$495,000				
Start Date	02/18/88				
Completion Date	05/02/88				
Name	Arsenic Mines	Other A residential well contained high levels of arsenic, possibly from material moved from the tailings pile.	Metals	Drinking Water Contamination Groundwater Contamination	Sampling/Analysis Provided Bottled Water Constructed Cistern
City	Kent				
State	NY				
NPL	N				
Cost	$69,600				
Start Date	03/24/88				
Completion Date	09/29/88				
Name	Bern Metals	Inactive Production Facility An abandoned metal recovery facility is located in a mixed residential/light industry area approximately one mile from the Buffalo River.	Metals Acids	Direct Contact	Site Security Sampling/Analysis
City	Buffalo				
State	NY				
NPL	N				
Cost	$48,000				
Start Date	04/21/88				
Completion Date	07/08/88				

+Note: Previous removal was completed at site. See Introduction for details.

REGION 2

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Clothier Disposal **City** Granby **State** NY **NPL** Y **Cost** $925,000 **Start Date** 10/07/86 **Completion Date** 07/22/88	Inactive Waste Management Facility Approximately 2,200 crushed, burned, punctured or rusted drums of industrial waste were disposed of in an unsecured area consisting primarily of farmland with wood lots and interconnected wetlands. A dirt access road separated this site from an active farm.	PCBs Volatile Organics Solvents	Direct Contact Fire/Explosion Hazard Food Chain Contamination Groundwater Contamination Surface Water Contamination	Site Security Sampling/Analysis Migration Control Containment/Retention Overpacked Drums Bulked Materials Solidified Materials Organized Materials Excavation Disposal AT: Thermal Destruction
Name Fort Ann **City** Village of Fort Ann **State** NY **NPL** N **Cost** $2,000 **Start Date** 03/01/88 **Completion Date** 03/11/88	Other A private residential well within 50 yards of a facility, which formulates and distributes pesticides and herbicides, was contaminated.	Pesticides	Groundwater Contamination	Sampling/Analysis Provided Bottled Water
Name High View Terrace **City** West Seneca **State** NY **NPL** N **Cost** $435,521 **Start Date** 03/24/88 **Completion Date** 04/22/88	Other EPA received a request to limit access, remove waste and decontaminate a vacant lot that was in close proximity to two elementary schools.	Cyanide Sulfide	Direct Contact	Site Security Sampling/Analysis Disposal
Name Hudson River (CG) **City** New York **State** NY **NPL** N **Cost** $3,771 **Start Date** 02/10/88 **Completion Date** 02/10/88	Other The Coast Guard was contacted by New York State to remove drums of unknown contents from the Hudson River.	Non-Hazardous Materials	Surface Water Contamination	Sampling/Analysis Disposal

+Note: Previous removal was completed at site. See Introduction for details.

REGION 2

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Lincoln Avenue / P.J. **City** Port Jefferson **State** NY **NPL** N **Cost** $23,000 **Start Date** 07/10/87 **Completion Date** 02/25/88	Other Four residential wells were contaminated. One of these wells exceeded EPA's 10-day Health Advisory for trichloroethylene.	Volatile Organics Solvents	Direct Contact Drinking Water Contamination	Sampling/Analysis Provided Bottled Water Provided Hookups to Water Main Site Restoration
Name Mattiace Petrochemicals Company **City** Glenwood Landing **State** NY **NPL** Y **Cost** $480,000 **Start Date** 02/05/88 **Completion Date** 06/15/88	Inactive Waste Management Facility Approximately 80 55-gallon drums and 100 5-gallon containers, many deteriorated and leaking, were scattered throughout the site. The area is aproximately 150 yards from a residential area, 3,700 feet from a public water supply well and directly adjacent to a state nature preserve.	PCBs Volatile Organics Acids Bases Solvents	Direct Contact Fire/Explosion Hazard	Site Security Sampling/Analysis Bulked Material Solidified Materials Disposal AT: Thermal Destruction
Name Miller Ave. **City** Amityville **State** NY **NPL** N **Cost** $7,000 **Start Date** 02/19/88 **Completion Date** 07/21/88	Other Five private residential wells, which served as the sole source of potable water, exceeded the removal action level for tetrachloroethylene and trichloroethylene contamination.	Solvents	Drinking Water Contamination Groundwater Contamination	Sampling/Analysis Provided Bottled Water Provided Hookups to Water Main
Name Minor Spill / Youngstown (CG) **City** Youngstown **State** NY **NPL** N **Cost** $614 **Start Date** 03/15/88 **Completion Date** 05/05/88	Other One drum on a Coast Guard station was leaking.	Unknown	Direct Contact	Sampling/Analysis Disposal

+Note: Previous removal was completed at site. See Introduction for details.

REGION 2

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name North Bloomfield **City** Lima **State** NY **NPL** N **Cost** $681,899 **Start Date** 12/02/85 **Completion Date** 06/03/88	Other Various volatile organics had been detected in wells at 32 private residences and one business with 60 employees.	Volatile Organics Solvents	Drinking Water Contamination Groundwater Contamination	Sampling/Analysis Provided Bottled Water Provided Hookups to Water Main
Name Pollution Abatement Services **City** Oswego **State** NY **NPL** Y **Cost** $445,118 **Start Date** 04/23/87 **Completion Date** 10/21/87	Inactive Waste Management Facility A 15-acre private incinerator site contained over 15,000 deteriorated and leaking drums and three lagoons holding 1.4 million gallons of chemicals and oils. These lagoons posed a threat of release into a creek that was 1,800 feet from Lake Ontario. Wetlands surrounded the site on three sides. Several residents were located 0.3 mile away, some of whom continued to use private wells for drinking water.	PCBs Volatile Organics Non-Volatile Organics Waste Oils	Direct Contact Fire/Explosion Hazard Groundwater Contamination Soil Contamination Surface Water Contamination	Site Security Sampling/Analysis Pumped Contaminants Migration Control Containment/Retention Overpacked Drums Disposal AT: Mobile Activated Carbon Trailer
Name Signo Trading / Mount Vernon **City** Mount Vernon **State** NY **NPL** N **Cost** $1,777,600 **Start Date** 12/08/86 **Completion Date** 11/25/87	Inactive Waste Management Facility A three-story warehouse in a densely populated area contained numerous types of chemicals, boxes and drums and housed a commercial facility.	Dioxin Volatile Organics Non-Volatile Organics Pesticides Acids Bases Solvents	Direct Contact Fire/Explosion Hazard	Site Security Sampling/Analysis Excavation Disposal Detonation AT: Potassium Polyethylene Glycol (KPEG) Process AT: Thermal Destruction
Name Town of Pompey **City** Pompey **State** NY **NPL** N **Cost** $79,000 **Start Date** 05/22/87 **Completion Date** 07/08/88	Other Residental wells exceeded the EPA 10-day Health Advisory for volatile organic compounds levels.	Volatile Organics Solvents	Groundwater Contamination	Sampling/Analysis Pumped Contaminants Neutralized Materials AT: Air Stripping

+Note: Previous removal was completed at site. See Introduction for details.

U. S. EPA REGION 3



ALSO: DC

For Information Contact:

Chief, Superfund Branch,
Hazardous Waste Management Division
841 Chestnut Street
Philadelphia, PA 19107
(215) 597-8132



REGION III COMPLETIONS LISTED IN VOLUMES I AND II

DELAWARE
Army Creek Landfill
Delaware River II - CG
Delaware Sand & Gravel Landfill
Dover Air Force Base
Harvey & Knott Drum Site
New Castle Containers
Sealand Ltd.
Tybouts Corner Landfill

MARYLAND
Baltimore Iron & Metals - CG
California MD Drum
Capitol Assay Labs
Cecil County Dump
Chemical Metals Industries
Columbia Park Drum
Evans Trail
Kane & Lombard Street Drums
Locomotive Junkyard - CG
Middletown Road Dump
Sand, Gravel & Stone
Security Boulevard
Southern Maryland Wood Treating
Springer Septic Services - CG
Union Plating
United Rigging & Hauling

PENNSYLVANIA
ABM Eddystone
Ambler Asbestos Piles
Apache Waste Oil
Ashland Chemical
Bensalem Drum
Berks Sand Pit - Van Ellswyck
BFG Electroplating
Biedler Road
Boyertown Scrap Metal
Brodhead Creek
Brown's Battery Breaking
Bruin Lagoon
Buried Drum Removal
Butler Tunnel
C & F Chemical

PENNSYLVANIA (Cont.)
C. E. Brubaker
Camp Run Drum
Caustic Midnight Dump
Dorney Road Landfill
Dracup Warehouse
Drake Chemical
Duncasville Tanker
Dunning Mountain Drum Fire
Durham Twp Solvent Spill
East Cumberland Street
Eweing Road Drum Site
Fennel Road
Garage Fire
Gradyville Midnight Dump
High Quality Plating
Howard Rodger's Drum
Interstate Transformer
Johnson Bronze
Keyser Ave. Borehole
Krum Trash
Lackawanna Refuse
Lancaster Battery
Malitovsky Drum Co.
Mercer County Drum Dump
Metcoa Radiation
Mill Creek Dump
Mt. Pocono
Old American Glycerine - Lewis Run
Old Garage
Pagan Road
Patrick Diehl
Piney Creek Drum
Pottstown Abandoned Trailer
Printed Circuits, Inc.
Revere Chemical Co.
Rotunda Drive
Route 13 Drum Site
SSCD Schoolyard Site
Sandonelle PCB
Satellite/Ammet Incendiary
Starbrick
Sunset Golf Course
Swissvale Auto
Taylor Borough Dump
Thorn Run Spill
Tinicum Marsh
Tri-State Engineering
Trowbridge Estates Mercury
Turco Coatings
Tysons Dump

PENNSYLVANIA (Cont.)
Vulcanized Rubber & Plastics
Wade (ABM)
Westinghouse Elevator Co.
Westline Site
Whitemarsh Twp Drum

VIRGINIA
Bent Creek/James River
C&R Battery Co. Inc.
Chesapeake Bay-CG
Hampton Cylinders Site
Lynnhaven Bay-CG
Rhinehart Tire Fire Dump
Roanoke River Drums
Tidewater TNT
Walkerton Tire Fire

WEST VIRGINIA
Big John's Salvage
Big John's Salvage - Hoult Road
Bittle Well Contamination
Chesapeake PCB Site
Clark Property
Coons Run
Edwards Road
Greenbriar River Flood
Harris Property
Harrison Co. PCB Spill
Holder Corporation
Interstate 70 Acid Spill
Kabletown Road
Knapp Creek
Leetown Pesticide
Manilla Creek
Richardson Property
Semco PCB Site
Stoneman Property
Walter Taylor
Wheeling Acid Spill
Wheeling Hill
Yokum Chlordane Contamination

REGION 3

Superfund Emergency Response Actions

Site Information		Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name	Atlantic Ave	Other	Volatile Organics	Direct Contact	Site Security
City	Elsmere	Several buried drums in poor condition were discovered by workers excavating a sidewalk. Site is within 500 feet of approximately 50 residences and about 50 feet south of Chestnut Run Creek, which feeds into the Christina River.			Sampling/Analysis
State	DE				Excavation
NPL	N				Overpacked Drums
Cost	$35,000				Organized Materials
Start Date	05/11/87				Site Restoration
Completion Date	04/22/88				AT: Thermal Destruction
Name	Delaware Bay Drum (CG)	Other	Metals	Direct Contact	Sampling/Analysis
City	Camden	A 55-gallon drum containing 20 gallons of an unknown hazardous waste was recovered by a crabber who brought the drum home.			Overpacked Drums
State	DE				Disposal
NPL	N				
Cost	$5,000				
Start Date	08/25/87				
Completion Date	12/14/87				
Name	Iron Hill Road Drum Site	Inactive Production Facility	Volatile Organics	Fire/Explosion Hazard	Site Security
City	Elkton	Approximately 300 drums and containers, some leaking, were in and around two buildings on a 4-acre site used for light industrial purposes. A preliminary assessment revealed high levels of volatile organic compounds in the soil, evidence of vandalism, and unrestricted site access.	Solvents	Soil Contamination	Sampling/Analysis
State	MD				Overpacked Drums
NPL	N				Excavation
Cost	$1,124,000				Bulked Materials
Start Date	03/05/87				Organized Materials
Completion Date	03/04/88				Monitored Wells
					Disposal
					AT: Thermal Destruction
Name	Oakland Junk Yard Site	Midnight Dump	Pesticides	Direct Contact	Sampling/Analysis
City	Oakland	Two abandoned tractor trailers discovered during a criminal investigation contained 150 deteriorated and leaking drums. The site is within 100 yards of residences and 0.5 miles from the city of Oakland.	Acids	Drinking Water Contamination	Overpacked Drums
State	MD		Bases	Fire/Explosion Hazard	Disposal
NPL	N		Solvents		
Cost	$257,250				
Start Date	11/26/86				
Completion Date	03/28/88				

+ Note: Previous removal was completed at site. See Introduction for details.

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Trans Tech/Adamstown **City** Frederick County **State** MD **NPL** N **Cost** $145,000 **Start Date** 05/24/86 **Completion Date** 10/02/87	Active Production Facility Groundwater at this site was found to be contaminated as a result of the improper disposal of solvents.	Solvents	Air Contamination/Inhalation Direct Contact Drinking Water Contamination Groundwater Contamination	Provided Bottled Water Provided Hookups to Water Main AT: Physical Carbon Adsorption AT: Physical Air-Stripping
Name American Insulator Co. **City** New Freedom **State** PA **NPL** N **Cost** $249,000 **Start Date** 11/03/86 **Completion Date** 10/16/87	Inactive Production Facility This site is an abandoned plastic molding facility with a variety of solvents, lacquers and coatings stored haphazardly in and around deteriorating buildings and two small laboratories.	Acids Solvents	Direct Contact Fire/Explosion Hazard Soil Contamination Surface Water Contamination	Site Security Sampling/Analysis Organized Materials AT: Thermal Destruction
Name American Street Tannery **City** Philadelphia **State** PA **NPL** N **Cost** $1,040,000 **Start Date** 08/06/87 **Completion Date** 07/14/88	Inactive Production Facility Approximately 350-400 drums and 200-300 laboratory-size containers of chemicals used by at least three tanning companies were stored in and around an abandoned building. Open vats holding unidentified solution were also located in this heavily vandalized building. The site is an urban area surrounded by rowhouses and bordered on one side by a carriage service keeping a number of horses.	Volatile Organics Acids	Direct Contact Fire/Explosion Hazard	Site Security Sampling/Analysis Organized Materials Disposal Detonation AT: Thermal Destruction
Name Donegal Twp Midnight Drum **City** Butler County **State** PA **NPL** N **Cost** $30,000 **Start Date** 03/13/87 **Completion Date** 10/30/87	Midnight Dump Three 55-gallon drums of unknown material were dumped on private property approximately 50 yards upgradient of a river.	Cyanide Volatile Organics Metals Solvents	Direct Contact Fire/Explosion Hazard	Sampling/Analysis Overpacked Drums Disposal

+ Note: Previous removal was completed at site. See Introduction for details.

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Eager Beaver Lumber Co **City** Townville **State** PA **NPL** N **Cost** $70,000 **Start Date** 02/01/88 **Completion Date** 09/07/88	Inactive Production Facility A 3,000-gallon lumber dip tank used for wood treating operations discharged chemicals onto the soil and into a nearby pond. An estimated 2,500 gallons were discharged annually from 1983 to 1986, killing fish and vegetation. The site is located in a rural/residential area within 300 yards of ten residences.	Volatile Organics Pesticides Solvents	Soil Contamination Surface Water Contamination	Site Security Sampling/Analysis Migration Control Containment/Retention Excavation Organized Materials Temporary Storage
Name Front Street Tanker **City** Chester **State** PA **NPL** N **Cost** $20,000 **Start Date** 08/09/88 **Completion Date** 09/07/88	Inactive Production Facility EPA was asked to investigate a leaking tanker, drums and stained soil.	Non-Hazardous Materials	Direct Contact	Site Security Sampling/Analysis Overpacked Drums Organized Materials Excavation Temporary Storage
Name Hutchinson Mine Site **City** Hutchinson **State** PA **NPL** N **Cost** $130,000 **Start Date** 10/15/87 **Completion Date** 04/01/88	Other Eight transformers at an unused electrical substation were vandalized resulting in the release of PCB-contaminated oil. The substation is located in a residential area and has experienced a high frequency of vandalism.	PCBs	Direct Contact Soil Contamination	Site Security Sampling/Analysis Excavation Neutralized Materials Organized Materials Site Restoration Disposal
Name Johnson Bronze **City** New Castle **State** PA **NPL** N **Cost** $6,596 **Start Date** 09/01/85 **Completion Date** 10/30/87	Inactive Production Facility The site consisted of approximately eight acres of inactive manufacturing buildings and chemical laboratories. Containers were open and in poor condition and chemicals were stored with no regard to compatability.	Cyanide Volatile Organics Acids	Air Contamination/Inhalation Direct Contact	Site Security Overpacked Drums Organized Materials Temporary Storage

+ Note: Previous removal was completed at site. See Introduction for details.

REGION 3

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Kevak Property **City** Glen Lyon **State** PA **NPL** N **Cost** $50,000 **Start Date** 02/11/87 **Completion Date** 11/01/87	Other An abandoned basement laboratory contained approximately 200 chemical containers. A resident lived directly above the basement and the site was in a residential neighborhood.	Cyanide Volatile Organics Acids	Direct Contact Fire/Explosion Hazard	Sampling/Analysis Overpacked Drums Disposal Detonation
Name Lansdowne Radiation Site **City** Lansdowne **State** PA **NPL** Y **Cost** $262,000 **Start Date** 09/18/84 **Completion Date** 08/01/88	Other Significant levels of gamma radiation and radon daughters were discovered in a duplex residence where a professor manufactured radium sources for medical use in the 1920s-1940s.	Low-Level Radioactive Waste	Direct Contact	Site Security Sampling/Analysis Temporary Relocation Decontamination Disposal Installed Fire Suppression Systems
Name Lansdowne Site #2 **City** Lansdowne **State** PA **NPL** N **Cost** $652,559 **Start Date** 04/08/85 **Completion Date** 04/29/88	Other Three "hot" old metal cabinets in the basement of a residence were the source of excessive gamma and alpha radiation. It is believed that they were brought from the Lansdowne Site where a professor processed radium 40 years ago.	Low-Level Radioactive Waste	Air Contamination/Inhalation Direct Contact	Sampling/Analysis Decontamination Excavation Disposal
Name National Vulcanized Fiber **City** Kennett Square **State** PA **NPL** N **Cost** $3,000 **Start Date** 12/11/87 **Completion Date** 05/26/88	Active Production Facility Heating oil containing PCBs entered a facility's cooling water outfall, which eventually discharged into the west branch of Red Clay Creek. Elevated levels of PCBs were found in fish tissue samples. The site is located in a rural/residential area next to a mushroom farm.	PCBs	Direct Contact Soil Contamination Surface Water Contamination	Site Security Sampling/Analysis

+ Note: Previous removal was completed at site. See Introduction for details.

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Nickel Plate Road **City** Cochranton **State** PA **NPL** N **Cost** $15,500 **Start Date** 01/18/88 **Completion Date** 03/24/88	Midnight Dump Three abandoned 55-gallon drums containing PCBs were discovered along French Creek flood plain. The site is located in a rural area with the nearest residence approximately 0.3 miles away.	PCBs	Direct Contact	Sampling/Analysis Overpacked Drums AT: Thermal Destruction
Name Paoli Rail Yard **City** Paoli **State** PA **NPL** Y **Cost** $1,752,100 **Start Date** 02/26/86 **Completion Date** 06/16/88	Active Production Facility This unsecured and easily accessible site was contaminated with PCBs from electrical transformer repairs. The ten acre site is surrounded on three sides by residential areas. Off-site contamination was believed to exist.	PCBs	Direct Contact	Site Security Sampling/Analysis Migration Control Containment/Retention Excavation Capping Site Restoration Disposal
Name Route 563 Drum Site **City** Salford Twp **State** PA **NPL** N **Cost** $10,000 **Start Date** 06/04/87 **Completion Date** 02/08/88	Midnight Dump State police discovered one drum in a drainage ditch two feet off a heavily traveled road.	Solvents	Direct Contact Fire/Explosion Hazard	Site Security Sampling/Analysis Overpacked Drums Disposal
Name Solly Ave. Midnight Dump **City** Philadelphia **State** PA **NPL** N **Cost** $40,000 **Start Date** 05/02/87 **Completion Date** 10/31/87	Midnight Dump Fifteen unmarked damaged and leaking drums were abandoned on property behind a newly constructed housing development.	Volatile Organics	Direct Contact Fire/Explosion Hazard	Overpacked Drums Disposal

+ Note: Previous removal was completed at site. See Introduction for details.

REGION 3

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Wach's Landfill **City** S Huntingdon **State** PA **NPL** N **Cost** $285,000 **Start Date** 04/08/87 **Completion Date** 01/15/88	Active Waste Management Facility Approximately 160 deteriorating and leaking drums from active landfill and metal recycling facility compose the site.	Volatile Organics Metals	Direct Contact Fire/Explosion Hazard Soil Contamination	SiteSecurity Sampling/Analysis Overpacked Drums Excavation Organized Materials Disposal
Name Greenwood Chemical Company **City** Greenwood **State** VA **NPL** Y **Cost** $1,200,701 **Start Date** 10/15/87 **Completion Date** 06/20/88	Inactive Waste Management Facility Four lagoons on the site of an inoperable small batch chemistry plant contained 300,000 gallons of contaminated water, approximately 700 buried drums and 250 drums on the surface. Many lab packs and small containers of unknown materials were on the surface or partially buried.	Cyanide Volatile Organics Biological Waste	Direct Contact Fire/Explosion Hazard Soil Contamination	Sampling/Analysis Migration Control Pumped Contaminants Neutralized Materials Excavation Overpacked Drums Organized Materials Disposal
Name Mathews Electric Plating **City** Roanoke **State** VA **NPL** Y **Cost** $45,000 **Start Date** 03/26/88 **Completion Date** 08/16/88	Inactive Production Facility Liquid electroplating waste from an auto bumper repair facility was discharged onto the ground causing chromium contamination of some local residential wells. Above ground storage tanks with approximately 3,000 gallons each, and four 55-gallon drums were also located on site.	Metals	Soil Contamination	Sampling/Analysis Pumped Contaminants Excavation Overpacked Drums Site Restoration Disposal
Name Atwell Mountain Drum Site **City** Atwell **State** WV **NPL** N **Cost** $85,000 **Start Date** 09/01/87 **Completion Date** 02/07/88	Midnight Dump Fourteen drums, 3 of which were labeled "poisonous" and 4 others marked "solid waste," were illegally dumped near a church. The drums were in poor condition and some were open and leaking a white solid material.	Cyanide	Air Contamination/Inhalation Direct Contact Soil Contamination	Site Security Sampling/Analysis Excavation Overpacked Drums Organized Materials Disposal

+ Note: Previous removal was completed at site. See Introduction for details.

REGION 3

Superfund Emergency Response Actions

Site Information		Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name	Cummings Landfill	Midnight Dump	Solvents	Direct Contact	Site Security
City	Hurricane	Sixty-one drums were illegally dumped in a salvage yard 200 feet from a home and approximately 1500 feet from Robinson Fork Creek. Several drums leaked and stained the soil; twenty-four were empty.		Soil Contamination	Sampling/Analysis
State	WV				Excavation
NPL	N				Overpacked Drums
Cost	$78,000				Organized Materials
Start Date	09/16/87				Disposal
Completion Date	02/11/88				AT: Thermal Destruction
Name	Garfield Street Drum	Midnight Dump	Acids	Direct Contact	Sampling/Analysis
City	McMechen	Two 10-gallon plastic containers filled with unknown corrosives were abandoned near a private residence. The substance had a pH of 14.			Overpacked Containers
State	WV				Disposal
NPL	N				
Cost	$20,000				
Start Date	08/17/87				
Completion Date	12/14/87				
Name	Keystone Drive Pesticide Dump	Midnight Dump	Pesticides	Direct Contact	Bulked Materials
City	Charleston	Three plastic jugs, cans, and liquid pesticide were dumped near a river, contaminating the soil and a roadway. Children had been seen playing near the site.		Soil Contamination	Excavation
State	WV				Organized Materials
NPL	N				Disposal
Cost	$35,000				
Start Date	07/25/87				
Completion Date	12/04/87				
Name	Lakin State Farm	Other	PCBs	Direct Contact	Sampling/Analysis
City	Chester	Four drums of capacitors and nine loose capacitors were on this rural site, leaking oil and contaminating the surrounding soil.		Soil Contamination	Excavation
State	WV				Bulked Materials
NPL	N				Disposal
Cost	$35,000				
Start Date	08/27/87				
Completion Date	12/14/87				

+ Note: Previous removal was completed at site. See Introduction for details.

REGION 3

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Petersburg Flood **City** Petersburg **State** WV **NPL** N **Cost** $26,000 **Start Date** 07/07/86 **Completion Date** 02/01/88	Active Production Facility Approximately 500-1000 pounds of wastes were stored in open trash cans and on pallets in an unsecured fertilizer warehouse after a major flood in November 1985. There was potential for contamination of bulk fertilizer sold for agricultural use.	Volatile Organics Pesticides	Air Contamination/Inhalation Direct Contact Food Chain Contamination	Sampling/Analysis Excavation Bulked Materials Organized Materials Disposal
Name Precious Metals Inc. **City** Beckley **State** WV **NPL** N **Cost** $40,000 **Start Date** 06/19/86 **Completion Date** 10/31/87	Midnight Dump Four drums containing muriatic acid and cyanide were abandoned at the site.	Cyanide Acids	Air Contamination/Inhalation Direct Contact	Overpacked Drums Disposal
Name Ray York Body Shop **City** Oak Hill **State** WV **NPL** N **Cost** $60,000 **Start Date** 08/12/87 **Completion Date** 02/29/88	Inactive Production Facility Approximately 20 drums of paint wastes in solvents were illegally dumped at an abandoned auto body facility in the center of a moderately sized housing development. Ten of the 20 drums were empty, while 2 others were sealed firmly.	Volatile Organics Solvents	Air Contamination/Inhalation Direct Contact Soil Contamination	Site Security Sampling/Analysis Overpacked Drums Organized Materials Excavation Disposal
Name Ridgeview PCB Site **City** Boone Co. **State** WV **NPL** N **Cost** $40,265 **Start Date** 07/22/87 **Completion Date** 12/04/87	Inactive Production Facility Five transformers containing PCB-contaminated oil were deserted at this facility. One had been knocked on its side, spilling oil and contaminating the soil.	PCBs	Direct Contact Soil Contamination	Organized Materials Excavation Disposal

+ Note: Previous removal was completed at site. See Introduction for details.

REGION 3

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Sasser Electric Co. Drum Site **City** Mt. Hope **State** WV **NPL** N **Cost** $35,000 **Start Date** 05/26/87 **Completion Date** 04/18/88	Inactive Production Facility Drums were discovered in mixed business/residential neighborhood. One drum had spilled PCBs onto concrete pavement.	PCBs	Direct Contact	Sampling/Analysis Overpacked Drums Excavation Neutralized Materials Disposal Site Restoration
Name Shaffer Equipment Co. **City** Minden **State** WV **NPL** N **Cost** $3,626,443 **Start Date** 12/28/84 **Completion Date** 12/20/87	Active Production Facility This site was an unsecured, active firm which was contaminated throughout with PCBs. Approximately 90 transformers, 107 capacitors and 55 drums of various chemicals were onsite, and both vandalism and off-site migration had been observed.	PCBs Acids	Direct Contact Soil Contamination Surface Water Contamination	Site Security Sampling/Analysis Migration Control Excavation Disposal AT: Thermal Destruction
Name Upper Glade Drum **City** Upper Glade **State** WV **NPL** N **Cost** $30,000 **Start Date** 08/04/87 **Completion Date** 12/14/87	Midnight Dump A leaking drum of unknown material was illegally dumped along a road, producing a large area of stressed vegetation. A local child became ill after coming in contact with the drum.	Solvents	Direct Contact Soil Contamination	Sampling/Analysis Overpacked Drums Excavation AT: Thermal Destruction
Name Upshur County 4-H Tarpit **City** Selbyville **State** WV **NPL** N **Cost** $80,000 **Start Date** 04/19/88 **Completion Date** 06/21/88	Inactive Production Facility The 3/4-acre tarpit located at an abandoned chemical company was utilized as a disposal area for the plant's wastes.	Volatile Organic	Direct Contact	Site Security Sampling/Analysis Migration Control Containment/Retention Capping Site Restoration

+ Note: Previous removal was completed at site. See Introduction for details.

U. S. EPA REGION 4

For Information Contact:

Chief, Emergency and Remedial Response Branch,
Waste Management Division
345 Courtland Street, N.E.
Atlanta, GA 30365
(404) 347-4097

Preceding page blank

REGION IV COMPLETIONS LISTED IN VOLUMES I AND II

ALABAMA
Callahan Drum
Church of God Property
Ingram Property
McAllister Drum Site
Mowbray Engineering Co.
Newfound Road
Petro Chemical
Turkey Creek Barrel Dump

FLORIDA
Abandoned Drum - CG
Abandoned Drum/Hillsborough - CG
Abandoned Drum/Marathon - CG
American Creosote/Pensacola
Beached Drum - CG
City Industries Inc.
Coleman - Evans Wood Pres. Co.
Creosote Tanks Release (Talleyrand)
Ellis Road
Hipps Road Landfill
Hollingsworth Solderless
Lake Worth Inlet - CG
Lummis Island - CG
PCB Midnight Dump
Pembroke Pines
Pepper Steel & Alloys, Inc.
Persons Property PCB Drums
Petroleum Products (Pembroke Rd.)
Pioneer Sand Co.
Sand Key - CG
Snapper Lane - CG
St. John River - CG
Tower Chemical Co.
Tri-City Oil Conservationist, Inc.
Unknown Chemical Discharge - CG
Whitehouse Oil Pits
Williams Pesticide Site
Yellow Water Road Dump

GEORGIA
Barnes Mill Drum
Barrow County Drum Site
Berrien Products
Buford Highway
Cascade Road
Catoosa County Labpack
Davis Farm
Eastern Chemcial Co.
Ft. Oglethorpe Drum
Gail Foster Property
Georgia Highway 138
Hadaway Road
Head PCB Spill
Helton Road
Hollywood Cemetary
Ivy Road (Bessie Runner)
Johnson Property Site
Kenyon Street Drum
Lake Kathy Road Spill
Linecrest Way
Marietta Road
Marzone Chemical Co.
McDonald Farm
Naomi Drum
Nashville Pesticide Site
Newnan Landfill
Old Laramore Ltd.
Payco Pallet & Drum
Pulverizing Plant Drum
Rock Bridge Park
Rome Coal Tar
Roosevelt Highway Spill
Salvo Property
Simpson Road Drum
Swainsboro Printworks
Sweetwater Creek Drums
U.S. Customs Pesticide
Villa Rich - High Point Rd.
Woodward Mill Road
Zenith Chemical

KENTUCKY
A.L. Taylor (Valley of the Drums)
Bowling Green Toxics
Chenault Rectifiers
Coal Branch Hollow
Distler Brickyard
Distler Farm
George O' Bryan Site
Harrison
Keith Farm Pond
Midnight Dumping (KY)
Nichro Plating Co.
Smith's Farm
Whitley County

MISSISSIPPI
Abandoned Drum Site
American Creosote Works (MS)
Benton Furniture Co.
Bergeron Marine
Canton Plating & Bumper Works
Caustic Chemical
Gulf Battery Exchange
Midnight Dump
Natchez Drug Site
Nesbit Scale House
Newsome Brothers/Old Reichold
Plastifax, Inc.
S. Electroforming
Sonford Products
Southern Lumber Co.

NORTH CAROLINA
Ahoskie Midnight Dump
Alandale Dr. Chemical
Auburn Church Road Drums
Beach Containers - CG
Buckhorn Pesticide Fire
Buckhorn Rd. Drum
Bush Brothers Plating
Caldwell County
Cape Fear Wood Preserving
Cape Hatteras National Seashore - CG
Carolina Transformer
Chemtronics, Inc.
Clayton Ballfield Pesticide
Davenport Creosote Spill
Dockery Property
DOT Maintenance Yard
Elizabeth City Drum
Everhart Lumber Site
Furnace Road Drum
Gillcrest Road
Hollingsworth Pesticide
Humpback Mtn. Rd. Drums
Laurel Springs PCB
Lenoir Refining
Macon Property
Midnight Dumping/Guilford
One-Hour Koretizing
Plymouth Wood Treatment
Potters Pits
Queens Property
Route 211 Pesticide Site
Rowes Corner Drum Dump
Salvage Oil of America
Sampson County Dumpster
Sanford Plating Co.
Scotts Creek Battery
South Riverdale Drive
U.S. 70 Dump
US Highway 1 Truck Site
Western Carolina Smelting

SOUTH CAROLINA
Babb Drums
Burkett Cylinder
C.D. Buff
Carolawn, Inc.
Dreyfus Street
Earl Allen Chemical Sites
Horry Co. Fireworks
Kershaw Co. Landfill
Jimmy's Truck Stop
Lando Drums
Medley Farm Drum Dump
National Galvanizing
Palmetto Wood Preserving
Reimer Drum
Woodward Property Drums

TENNESSEE
American Creosote/Jackson Plant
Arlington Blending
Gallaway Pits
Hamill - Hooker Rd. #3
J & L Drum Site
Jacques Miller Site (Kirby)
Miller Site

REGION 4

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name FMHA-USDA/Roy **City** Pine Level **State** AL **NPL** N **Cost** $105,000 **Start Date** 10/05/87 **Completion Date** 02/20/88	Other Approximately 400-500 drums of pesticides and herbicides were present on site. No waste management had been observed, with drums scattered all over the site, bulging and in bad condition.	Pesticides	Direct Contact	Excavation Bulked Materials Disposal
Name Garner Road Drum **City** Cordova **State** AL **NPL** N **Cost** $50,000 **Start Date** 11/12/87 **Completion Date** 01/06/88	Midnight Dump Fifty-three drums were illegally dumped just outside of Jasper, AL.	Solvents	Direct Contact Fire/Explosion Hazard	Sampling/Analysis Overpacking Drums Disposal
Name Edmond's Salvage Yard **City** Cross City **State** FL **NPL** N **Cost** $600,000 **Start Date** 12/07/87 **Completion Date** 12/21/87	Inactive Waste Management Facility The site is an abandoned 4-acre dump which was strewn with heavy metal-contaminated ash, transformers, old 55-gallon drums, asbestos, and assorted metal junk.	Asbestos Volatile Organics Metals	Direct Contact Groundwater Contamination Surface Water Contamination	Sampling/Analysis Excavation Bulked Materials Site Restoration Disposal
Name General Laminates **City** Jasper County **State** FL **NPL** N **Cost** $200,000 **Start Date** 04/11/88 **Completion Date** 06/27/88	Inactive Production Facility An abandoned laminating facility had 500 to 600 fifty-five gallon drums of hazardous waste stored in an open field. Some drums had no lids or were leaking.	Solvents	Direct Contact Fire/Explosion Hazard	Sampling/Analysis Excavation Bulked Materials Disposal AT: Thermal Destruction
Name Ordinance Research Institute **City** Ft. Walton Beach **State** FL **NPL** N **Cost** $45,000 **Start Date** 09/19/87 **Completion Date** 01/15/88	Inactive Production Facility Three thousand pounds of explosives, reactive materials, radioactive material, and flammable liquids and solids were abandoned at this site.	Volatile Organics Metals Solvents Low-Level Radioactive Waste	Air Contamination/Inhalation Direct Contact Fire/Explosion Hazard	Temporary Evacuation Neutralized Materials Disposal Detonation

+Note: Previous removal was completed at site. See Introduction for details.

REGION 4

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Worthington Spring Site **City** Worthington Spring **State** FL **NPL** N **Cost** $45,600 **Start Date** 10/13/87 **Completion Date** 01/20/88	Inactive Waste Management Facility Forty 55-gallon drums and eight 5-gallon drums were deserted onsite. Most of the drums were in poor condition and leaking. Private wells are within 30 yards.	Metals Solvents	Drinking Water Contamination	Sampling/Analysis Disposal
Name Bank County Drum **City** Atlanta **State** GA **NPL** N **Cost** $10,000 **Start Date** 05/20/87 **Completion Date** 10/27/87	Midnight Dump Five abandoned 55-gallon drums were deserted along a roadway. The drums were open and exposed to the weather. Much material was spilled on the ground.	Volatile Organics	Air Contamination/Inhalation Fire/Explosion Hazard	Sampling/Analysis Overpacked Drums Disposal AT: Thermal Distruction
Name Cobb County Drum **City** Marietta **State** GA **NPL** N **Cost** $8,000 **Start Date** 04/19/88 **Completion Date** 06/06/88	Midnight Dump EPA responded to six 55-gallon drums dumped on the side of a residental street.	Waste Oils	Direct Contact	Sampling/Analysis Bulked Materials Disposal
Name Dade County Drum **City** Trenton **State** GA **NPL** N **Cost** $10,000 **Start Date** 07/22/87 **Completion Date** 10/23/87	Midnight Dump Two 55-gallon drums were dumped on private property. The drums contained paint and solvent wastes. A child received minor burns while playing around the drums.	Solvents	Direct Contact	Overpacked Drums Disposal
Name Dickerson Post Treating **City** Homerville **State** GA **NPL** N **Cost** $855,000 **Start Date** 07/22/87 **Completion Date** 03/19/88	Inactive Production Facility This former wood treating facility contained one pressure cylinder, three storage tanks, two surface impoundments, and 252 open drums containing liquids. A well is 100 feet away.	Non-volatile Organics	Direct Contact Air Contamination/Inhalation Groundwater Contamination.	Bulked Materials Pumped Contaminants Excavation Disposal AT: Thermal Destruction

+Note: Previous removal was completed at site. See Introduction for details.

REGION 4

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Worthington Spring Site **City** Worthington Spring **State** FL **NPL** N **Cost** $45,600 **Start Date** 10/13/87 **Completion Date** 01/20/88	Inactive Waste Management Facility Forty 55-gallon drums and eight 5-gallon drums were deserted onsite. Most of the drums were in poor condition and leaking. Private wells are within 30 yards.	Metals Solvents	Drinking Water Contamination	Sampling/Analysis Disposal
Name Bank County Drum **City** Atlanta **State** GA **NPL** N **Cost** $10,000 **Start Date** 05/20/87 **Completion Date** 10/27/87	Midnight Dump Five abandoned 55-gallon drums were deserted along a roadway. The drums were open and exposed to the weather. Much material was spilled on the ground.	Volatile Organics	Air Contamination/Inhalation Fire/Explosion Hazard	Sampling/Analysis Overpacked Drums Disposal AT: Thermal Distruction
Name Cobb County Drum **City** Marietta **State** GA **NPL** N **Cost** $8,000 **Start Date** 04/19/88 **Completion Date** 06/06/88	Midnight Dump EPA responded to six 55-gallon drums dumped on the side of a residental street.	Waste Oils	Direct Contact	Sampling/Analysis Bulked Materials Disposal
Name Dade County Drum **City** Trenton **State** GA **NPL** N **Cost** $10,000 **Start Date** 07/22/87 **Completion Date** 10/23/87	Midnight Dump Two 55-gallon drums were dumped on private property. The drums contained paint and solvent wastes. A child received minor burns while playing around the drums.	Solvents	Direct Contact	Overpacked Drums Disposal
Name Dickerson Post Treating **City** Homerville **State** GA **NPL** N **Cost** $855,000 **Start Date** 07/22/87 **Completion Date** 03/19/88	Inactive Production Facility This former wood treating facility contained one pressure cylinder, three storage tanks, two surface impoundments, and 252 open drums containing liquids. A well is 100 feet away.	Non-volatile Organics	Direct Contact Air Contamination/Inhalation Groundwater Contamination.	Bulked Materials Pumped Contaminants Excavation Disposal AT: Thermal Destruction

+Note: Previous removal was completed at site. See Introduction for details.

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Marietta Mercury Spill **City** Marietta **State** GA **NPL** N **Cost** $1,000 **Start Date** 04/12/88 **Completion Date** 04/12/88	Other A resident reported that some six ounces of mercury spilled on the floor of her house. When EPA arrived, she had cleaned it up.	Metals	Direct Contact	No Actions
Name Mathis Brothers Chickamauga **City** Lafayette **State** GA **NPL** N **Cost** $30,000 **Start Date** 07/23/87 **Completion Date** 10/23/87	Active Waste Management Facility The site is an abandoned facility where 30 to 40 drums of lead were illegally landfilled. The drums were badly decayed with lead spilled from many of them.	Metals	Air Contamination/Inhalation Direct Contact Soil Contamination	Excavation Bulked Materials Disposal
Name Peachtree Mercury Spill **City** Norcross **State** GA **NPL** N **Cost** $10,000 **Start Date** 12/30/87 **Completion Date** 02/24/88	Other Mercury was spilled from a dumpster onto the parking lot of several businesses.	Metals	Direct Contact	Containment/Retention AT: Recycling
Name Rock Road Drum Spill **City** Greenville **State** GA **NPL** N **Cost** $8,000 **Start Date** 02/18/88 **Completion Date** 08/08/88	Midnight Dump Eight drums were illegally dumped by unknown parties. The drums contained ignitable substances and two of them leaked considerably.	Solvents	Direct Contact Fire/Explosion Hazard Soil Contamination	Excavation Overpacked Drums Disposal
Name A.L. Taylor + **City** Shepardsville **State** KY **NPL** Y **Cost** $50,000 **Start Date** 09/12/88 **Completion Date** 09/23/88	Inactive Waste Management Facility This13-acre dump and recycling center contained ignitable solvents and incompatable acids & bases. Solvents from approximately 4,200 drums were leaking into a tributary of the Ohio River.	PCBs Acids Bases Solvents	Groundwater Contamination Surface Water Contamination Soil Contamination Fire/Explosion Hazard	Site Restoration

+Note: Previous removal was completed at site. See Introduction for details.

REGION 4

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Greenup Tire Fire **City** Greenup **State** KY **NPL** N **Cost** $90,000 **Start Date** 06/07/88 **Completion Date** 06/18/88	Active Waste Management Facility An estimated 200,000 to 1,000,000 tires buried on a steep bank as erosion control caught fire. The Commonwealth of Kentucky requested EPA's assistance.	Pesticides Metals Acids Solvents	Direct Contact Air Contamination/Inhalation Surface Water Contamination	Extinguished Fire Migration Control Site Restoration Disposal
Name Industrial Plastics **City** Louisville **State** KY **NPL** N **Cost** $250,000 **Start Date** 02/04/88 **Completion Date** 07/12/88	Inactive Production Facility This site was an old plastisoiling operation that applied plastic coatings to steel. There were about 130 drums scattered on the surface and an unknown number of buried drums.	Asbestos Metals Solvents	Direct Contact Fire/Explosion Hazard Soil Contamination Surface Water Contamination	Sampling/Analysis Overpacked Drums Organized Materials Bulked Materials Disposal
Name Lee's Lane Landfill **City** Louisville **State** KY **NPL** Y **Cost** $1,800,000 **Start Date** 03/16/87 **Completion Date** 10/27/87	Inactive Waste Management Facility This site is a closed landfill where hazardous contaminants were identified in the soil, surface water, and groundwater on site.	Metals	Direct Contact Groundwater Contamination	Site Security Sampling/Analysis Migration Control Containment/Retention Capping Temporary Storage
Name Lee's Lane Landfill + **City** Louisville **State** KY **NPL** Y **Cost** $50,000 **Start Date** 09/14/88 **Completion Date** 09/27/88	Inactive Waste Management Facility Tis site is a closed landfill where hazardous contaminants were identified in the soil, surface water, and groundwater on site.	Metals	Direct Contact Groundwater Contamination	Site Restoration
Name Newport Dump **City** Newport **State** KY **NPL** Y **Cost** $2,646,400 **Start Date** 06/30/87 **Completion Date** 10/30/87	Inactive Waste Management Facility The site operated for 20 years as a municipal landfill. An installed leachate system was never operational and leachate had been observed leaking into the nearby river.	PCBs Metals	Groundwater Contamination Soil Contamination Surface Water Contamination	Site Security Containment/Retention Migration Control

+Note: Previous removal was completed at site. See Introduction for details.

REGION 4

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name O'Con Engineering **City** Bonnieville **State** KY **NPL** N **Cost** $120,000 **Start Date** 02/09/88 **Completion Date** 07/12/88	Active Production Facility The facility was previously occupied by a manufacturer of fiberglass. Approximately 5 drums containing paint cans were buried and 31 were stored on the property.	Solvents	Soil Contamination Fire/Explosion Hazard	Sampling/Analysis Bulked Materials Solidified Materials Containment/Retention Migration Control Overpacked Drums Disposal
Name Taylorsport Sand & Gravel **City** Taylorsport **State** KY **NPL** N **Cost** $100,000 **Start Date** 07/20/87 **Completion Date** 10/09/87	Inactive Waste Management Facility Approximately 100 drums were dumped in a sand pit along the Ohio River.	Volatile Organics	Fire/Explosion Hazard	Solidified Materials Disposal AT: Thermal Destruction
Name Tindall Property Transformer **City** Lawrenceberg **State** KY **NPL** N **Cost** $0 **Start Date** 11/30/87 **Completion Date** 12/21/87	Inactive Waste Management Facility Approximately 500 cubic yards of ash from various items, including transformers, were present on site. PCBs were present, and lead was leaching into an adjacent stream	PCBs Metals	Surface Water Contamination	Excavation Organized Materials Containment/Retention Disposal
Name Cowart Vacation Bible School **City** Tallahatchie City **State** MS **NPL** N **Cost** $40,000 **Start Date** 6/13/88 **Completion Date** 6/17/88	Other Three 55-gallon drums of calcium arsenate were accidentally spread across 1/4 acre by a bulldozer. One-hundred and three drums were then discovered beneath the surface.	Pesticides	Air Contamination/Inhalation Direct Contact	Site Security Excavation Overpacked Drums Site Restoration Disposal
Name Gooken Farms Drum **City** Senatobia **State** MS **NPL** N **Cost** $50,000 **Start Date** 6/15/87 **Completion Date** 10/22/87	Midnight Dump Approximately 42 drums were found in a drainage ditch one-quarter of a mile from a farm residence.	Solvents	Direct Contact	Sampling/Analysis Organized Materials Neutralized Materials Bulked Materials Disposal

+Note: Previous removal was completed at site. See Introduction for details.

REGION 4

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Newsome Bro./Old Reichold + **City** Columbia **State** MS **NPL** Y **Cost** $1,050,000 **Start Date** 11/03/87 **Completion Date** 02/08/88	Active Production Facility Over 3,600 drums of hazardous materials were left by a former owner. Also three lagoons and a 500-gallon tank filled with contaminants, and an empty 16,000-gallon tank were onsite.	PCBs Solvents	Fire/Explosion Hazard Groundwater Contamination	Excavation Bulked Materials Organized Materials Disposal
Name Barnes Property **City** Fairmont **State** NC **NPL** N **Cost** $26,250 **Start Date** 8/10/88 **Completion Date** 8/11/88	Midnight Dump A fire destroyed a warehouse where chemicals were stored, releasing hazardous materials into the environment.	Pesticides	Direct Contact Groundwater Contamination Soil Contamination Surface Water Contamination	Excavation Disposal
Name Bostic Drum **City** Holly Ridge **State** NC **NPL** N **Cost** $70,000 **Start Date** 08/11/87 **Completion Date** 10/12/87	Active Production Facility Ninety-eight drums of dinitrophenol were discovered inside a garage, many of them leaking. Several mobile homes are 600 feet from the garage.	Solvents	Direct Contact Air Contamination/Inhalation Fire/Explosion Hazard Surface Water Contamination	Overpacked Drums Disposal AT: Recycling
Name Carolina Production **City** Ashville **State** NC **NPL** N **Cost** $379,719 **Start Date** 09/14/87 **Completion Date** 01/29/88	Inactive Production Facility The facility contained numerous corroded drums and vats containing electroplating chemcials, solutions, and wastes.	Cyanide Metals	Air Contamination/Inhalation Direct Contact	Disposal AT: Solidified Materials
Name Cleveland Co. Drum **City** Shelby **State** NC **NPL** N **Cost** $5,000 **Start Date** 05/28/87 **Completion Date** 10/27/87	Midnight Dump Two unidentified drums were dumped behind a parking lot. One showed signs of leakage, the other was labeled "laquer thinner". A ditch was nearby.	Solvents	Direct Contact Fire/Explosion Hazard	Sampling/Analysis Organized Materials Disposal

+Note: Previous removal was completed at site. See Introduction for details.

REGION 4

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Cornell-Dublier Electronics **City** Sanford **State** NC **NPL** N **Cost** $450,000 **Start Date** 07/18/88 **Completion Date** 07/31/88	Inactive Production Facility Approximately 1,000 cubic yards of volatile and semi-volatile organic resins used in the manufacture of capacitators were buried in a resin trench on site.	Volatile Organics Solvents	Direct Contact Groundwater Contamination Soil Contamination Surface Water Contamination	Excavation Bulked Materials Pumped Contaminants Disposal
Name Forbush Metal Fabricators **City** Yadkinville **State** NC **NPL** N **Cost** $100,000 **Start Date** 10/14/87 **Completion Date** 04/27/88	Inactive Production Facility The site contained seven open and ruptured drums of zinc cyanide, sodium hydroxide, pthalates, and also a 1,200 cubic foot evaporation pit with the same contaminants.	Cyanide Non-volatile organics Metals Bases	Air Contamination/Inhalation	Sampling/Analysis Overpacked Drums Excavation Neutralized Materials Disposal
Name Gaston Co. Drum **City** Gastonia **State** NC **NPL** N **Cost** $8,000 **Start Date** 05/28/87 **Completion Date** 10/27/87	Midnight Dump Two unidentified drums were left onsite: one 55-gallon drum in poor condition with some liquid inside, and a nearly full 30-gallon drum labelled "alkaline material".	Volatile Organics	Direct Contact	Disposal
Name Gibson Midnight Drum **City** Gibson **State** NC **NPL** N **Cost** $9,500 **Start Date** 10/26/87 **Completion Date** 02/26/88	Midnight Dump Five drums of waste, including one that was leaking, were dumped by unknown persons.	Volatile Organics	Drinking Water Contamination Groundwater Contamination	Overpacked Drums Disposal
Name JMC Plating Co **City** Lexington **State** NC **NPL** N **Cost** $950,000 **Start Date** 02/04/88 **Completion Date** 08/12/88	Inactive Production Facility Approximately 60,000 gallons of plating sludge and 200 drums containing cyanide and heavy metals were deserted on site.	Cyanide Metals Acids Solvents	Air Contamination/Inhalation Soil Contamination	Site Security Sampling/Analysis Temporary Storage

+Note: Previous removal was completed at site. See Introduction for details.

REGION 4

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name PCB Contaiminated Wells **City** Taylorsville **State** NC **NPL** N **Cost** $13,400 **Start Date** 10/20/87 **Completion Date** 11/01/87	Other Lightning struck the submersible pumps of three wells, causing a rupture of the pump capacitors which contaminated the wells with PCBs.	PCBs	Drinking Water Contamination	Sampling/Analysis Pumped Contaminants Disposal AT: Physical Treatment Carbon Adsorption
Name Union Co Drum **City** Monroe **State** NC **NPL** N **Cost** $6,000 **Start Date** 05/29/87 **Completion Date** 10/27/87	Midnight Dump Two unidentified drums were placed on a pile of sand. The two drums, one 55-gallon and one 30-gallon, were nearly full and the smaller one had a hole.	Solvents	Direct Contact	Disposal
Name Woody's Tire Fire **City** Gastonia **State** NC **NPL** N **Cost** $90,000 **Start Date** 09/12/88 **Completion Date** 09/14/88	Active Waste Management Facility An estimated 90,000 tires buried three feet deep caught fire. The county fire department requested EPA's assistance.	Metals Solvents	Air Contamination/Inhalation Direct Contact Surface Water Contamination	Extinguished Fire Sampling/Analysis Migration Control Site Restoration Temporary Storage
Name Donaldson Roadside Spill **City** Greenville **State** SC **NPL** N **Cost** $20,000 **Start Date** 09/10/87 **Completion Date** 10/09/87	Midnight Dump An unknown party dumped paint solvents into a storm drain which drains to a lake. Explosive vapor levels were detected in the sewer.	Solvents	Air Contamination/Inhalation Direct Contact Fire/Explosion Hazard Soil Contamination Surface Water Contamination	Containment/Retention Pumped Contaminants Excavation Disposal
Name Geiger (C & M Oil) **City** Charleston **State** SC **NPL** Y **Cost** $100,000 **Start Date** 10/14/87 **Completion Date** 05/16/88	Inactive Waste Management Facility Between 1969 and 1971, eight lagoons were used on site to contain waste oils similar to automobile crankcase oils, prior to incineration.	PCBs Non-volatile Organics Metals	Direct Contact Groundwater Contamination	Sampling/Analysis Pumped Contaminants Disposal

+Note: Previous removal was completed at site. See Introduction for details.

REGION 4

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Inman Warehouse **City** Inman **State** SC **NPL** N **Cost** $110,000 **Start Date** 01/21/88 **Completion Date** 08/18/88	Other Approximately 130 containers, drums and carboys containing metal plating wastes were illegally stored at the Inman warehouse. Ninety percent of the containers were leaking.	Cyanide Metals	Air Contamination/Inhalation Direct Contact	Sampling/Analysis Overpacked Drums Disposal
Name Nichols Air Strip **City** Nichols **State** SC **NPL** N **Cost** $490,000 **Start Date** 04/05/88 **Completion Date** 05/27/88	Inactive Production Facility The site consisted of approximately one-half acre of soil contaminated with pesticides from an aerial spraying operation. A residential area is adjacent.	Pesticides	Direct Contact	Sampling/Analysis Excavation Disposal
Name Gallaway Pits+ **City** Gallaway **State** TN **NPL** Y **Cost** $690,000 **Start Date** 06/25/87 **Completion Date** 10/10/87	Other This 10-acre site contained a series of old gravel pits used for permitted dumping of wastes, including pesticides.	Pesticides	Direct Contact Drinking Water Contamination Groundwater Contamination Soil Contamination Surface Water Contamination	Site Security Sampling/Analysis Solidifed Materials Excavation Containment/Retention Capping Disposal

+Note: Previous removal was completed at site. See Introduction for details.

U. S. EPA REGION 5

For Information Contact:

Chief, Emergency and Enforcement Response Branch, Waste Management Division
230 S. Dearborn Street
Chicago, IL 60604
(312) 886-6236

REGION V COMPLETIONS LISTED IN VOLUMES I AND II

ILLINOIS
A & F Materials Reclaiming
Abandoned Drum
A-Chemical
Alburn Incinerator
Belvidere Municipal Landfill
Blue Cyanide Chips
Byron/Johnson Salvage Yard
Chicago Drum
Cyanide Incident
Danville Plating
Dead Creek
Floyd Hutter
Gebhart Fertilizer
Hixon Plating
LaSalle Electric Utilities
Liquid Dynamics
Sorrento Site
Stewart Drum
US Scrap

INDIANA
Abandoned Drum - CG
Bennett Stone Quarry
Bloomington Capacitor Site
Cantu Well
Dowden Landfill
Elkhart Site
Envirochem Corp.
Gary Dog Pound
I - 69
Indiana Refinery
Lake Sandy Jo (M&M Landfill)
Lemon Lane Landfill
Main Street Well
Meyers Dump
Michigan City Drums
Midco I
Midwest Plating
Midwest Plating-Kokomo
Monon Waterworks
Poer Farm
Portage Drums

INDIANA (Cont.)
R.J. Trucking
Seymour Recycling Corp.
Shelton Wells
Steel Container
Sycamore Street
Tyler Street Drums
Wedzeb Enterprises

MICHIGAN
Abandoned Drums - Ecorse
Berlin & Farro
Carter Industrial
Chemical Drum - CG
Drums on Beach - CG
Duell and Gardner Landfill
East Bay Site
Fort & Scotten Streets
International Disc Corp.
Liquid Disposal, Inc.
Midnight Dumping - Detroit
Millpoint (Spring Lake)
Mt. Elliot Drum
Niles Township
Northernaire Plating
Ott/Story/Cordova
PBM Enterprises
Peerless Plating
Rasmussen's Dump
Rose Township Dump
Saginaw Painting Co.
Verona Well Field

MINNESOTA
Bow Chemical
Isanti Solvent Sites
Lehillier/Mankato Site
Rumple Junkyard
St. Louis River - CG
Union Scrap Iron and Metal Co.

OHIO
Aeroquip/Republic Hose
American Steel Drum
Anaconda Road Site
Asbestos Bags
Central Waste landfill
Chem-Dyne
Chemical Minerals Reclamation
G P & K, Inc.
Greiners Lagoon
Hytech Chrome
J.C. Haynes
J.V. Peters
Laskin/Poplar Oil Co.
Liquid Waste Management
Old Mill
Petroleum Power & Maintainance
Raser Tannery
Seaway Warehouse
Skiljan/Dial
Summit Equipment & Supplies
Summit National
T.P. Long
United Scrap Lead Co.
Valleywood Subdivision
W. 58th Street Drum Site
Wade Park Chemicals

WISCONSIN
Better Brite - Chrome
C-Way
Malleable Range Co.
Oak Creek
Oconomowoc Electroplating Inc.
Reuping Leather Co.
Rodgers Laboratories
Schmalz Dump
Spectro Chemical
Wausau Groundwater Contamination

REGION 5

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Autocrat Corp **City** New Athens **State** IL **NPL** N **Cost** $135,000 **Start Date** 03/25/87 **Completion Date** 12/22/87	Inactive Production Facility There are approximately 50 55-gallon drums, four sludge tanks, 50 PCB capacitators, 12 fiber drums, 170 5-gallon pails, 50 cubic yards of foundry ash, and an asbestos boiler wrap in several deteriorated buildings.	PCBs Asbestos Volatile Organics Solvents	Air Contamination/Inhalation Direct Contact Fire/Explosion Hazard	Site Security Sampling/Analysis Organized Materials Neutralized Materials Bulked Materials Disposal AT: Thermal Destruction
Name Chem Pac **City** Chicago **State** IL **NPL** N **Cost** $44,800 **Start Date** 06/04/87 **Completion Date** 03/31/88	Inactive Production Facility Approximately 500 lab reagent bottles and pails were left in an abandoned lab.	Acids Bases Solvents	Direct Contact Fire/Explosion Hazard	Site Security Sampling/Analysis Bulked Materials Disposal
Name Lusher St. Groundwater **City** Elkhart **State** IN **NPL** N **Cost** $21,825 **Start Date** 11/27/87 **Completion Date** 12/31/87	Other During routine sampling the Elkhart County Health Dept. discovered high levels of contamination in private wells. Trichloroethene and trichloroethane are present.	Volatile Organics	Drinking Water Contamination	Provided Hookups to Water Main AT: Physical-Carbon Adsorption
Name Lusher St. Groundwater + **City** Elkhart **State** IN **NPL** N **Cost** $13,225 **Start Date** 06/09/88 **Completion Date** 08/31/88	Other Sampling by the County Health Dept. found further contamination in additional private wells. Trichloroethene and trichloroethane were present.	Volatile Organics	Drinking Water Contamination	Provided Hookups to Water Main AT: Physical-Carbon Adsorption
Name Ninth Ave. Dump **City** Gary **State** IN **NPL** Y **Cost** $92,500 **Start Date** 09/14/87 **Completion Date** 10/14/87	Midnight Dump About 10,000 drums were dumped indiscriminantly. They consisted of oil, paint, solvents, tires, resins, acids, and waste chemicals.	Metals Solvents	Direct Contact Ecological Damage Groundwater Contamination Soil Contamination	Site Security

+Note: Previous removal was completed at site. See Introduction for details.

REGION 5

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Tri-State Plating + **City** Columbus **State** IN **NPL** Y **Cost** $174,000 **Start Date** 11/06/87 **Completion Date** 12/18/87	Inactive Waste Management Facility Drums are indiscriminantly staged and there is evidence of soil contamination. Site is 800 feet from the city's secondary municipal wellfield.	Cyanide Metals	Direct Contact Air Contamination/Inhalation Groundwater Contamination	Excavation Pumped Contaminants Site Restoration Disposal
Name Westville Oil (Cam-Or) **City** Westville **State** IN **NPL** N **Cost** $1,418,000 **Start Date** 03/20/87 **Completion Date** 12/09/87	Inactive Waste Management Facility The facility's cooling pond, into which the site drains, was nearly full and had a history of overflowing. PCB contamination is documented at the site.	PCBs Solvents Volatile Organics	Direct Contact Groundwater Contamination Soil Contamination Surface Water Contamination	Site Security Sampling/Analysis Excavation Pumped Contaminants Solidified Materials Disposal AT: Dewatering/ Solidification
Name Cannelton Industries **City** Sault St. Marie **State** MI **NPL** Y **Cost** $100,000 **Start Date** 06/11/88 **Completion Date** 07/01/88	Inactive Production Facility The site was used as a landfill for tannery waste. Smouldering fires have been occuring for the past several years.	Metals	Direct Contact Fire/Explosion Hazard Surface Water Contamination	Site Security Sampling/Analysis Migration Control
Name International Disk Corp + **City** Ellsworth **State** MI **NPL** N **Cost** $361,400 **Start Date** 07/10/87 **Completion Date** 10/11/87	Inactive Production Facility Closed metal plating facility has contaminated plating baths, PCB transformers, painting equipment, waste, and friable asbestos.	PCBs Asbestos Cyanide Acids	Direct Contact Surface Water Contamination	Sampling/Analysis Bulked Materials Disposal

+Note: Previous removal was completed at site. See Introduction for details.

REGION 5

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Plating Equipment Used **City** Detroit **State** MI **NPL** N **Cost** $223,700 **Start Date** 08/06/87 **Completion Date** 12/31/87	Inactive Waste Management Facility An estimated 200 drums and 50 vats were found onsite, some with cyanide levels up to 100,000 parts per million. Soils were contaminated with cyanides and heavy metals.	Cyanide Metals Acids	Direct Contact Groundwater Contamination Soil Contamination Food Chain Contamination	Site Security Sampling/Analysis Overpacked Drums Excavation Disposal
Name Revere Copper + Brass **City** Detroit **State** MI **NPL** N **Cost** $58,000 **Start Date** 03/15/88 **Completion Date** 04/17/88	Inactive Production Facility PCB-contaminated oil was dumped from transformers onto the ground. Oil pools are within 20 feet of the Detroit River.	PCBs	Direct Contact Groundwater Contamination Surface Water Contamination	Sampling/Analysis Overpacked Drums Excavation Organized Materials Disposal
Name Selkirk-Benham St. **City** Detroit **State** MI **NPL** N **Cost** $23,500 **Start Date** 05/23/87 **Completion Date** 10/02/87	Midnight Dump Sixteen drums of rubber waste were dumped off of a pick-up truck at a residential property.	Solvents Non-Hazardous Materials	Air Contamination/Inhalation Direct Contact	Disposal
Name S.E.R. Plating **City** Kalamazoo **State** MI **NPL** N **Cost** $137,660 **Start Date** 04/29/87 **Completion Date** 10/12/87	Inactive Production Facility Approximately 20,000 gallons of hazardous waste were staged indiscriminantly on the site of a closed plating facility.	Cyanide Acids	Direct Contact Fire/Explosion Hazard	Site Security Disposal
Name Stevenson Road Drum **City** Clinton Township **State** MI **NPL** N **Cost** $10,800 **Start Date** 09/04/87 **Completion Date** 10/02/87	Midnight Dump A total of 101 unlabeled drums were dumped in the vicinity of Stevenson Road.	Acids Non-Hazardous Materials	Direct Contact Soil Contamination	Sampling/Analysis Overpacked Drums Disposal

+Note: Previous removal was completed at site. See Introduction for details.

REGION 5

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name American Steel Drum + **City** Bedford **State** OH **NPL** N **Cost** $1,036,621 **Start Date** 12/07/87 **Completion Date** 06/10/88	Inactive Production Facility A deteriorated building contained a 2,500-gallon pit and assorted wastes. The site also contained a large ash pile and an oil pit. PCB contamination was documented.	PCBS Cyanide Pesticide Metals Solvents	Direct Contact Soil Contamination Surface Water Contamination	Excavation Disposal
Name Chemco **City** Astabula **State** OH **NPL** N **Cost** $60,000 **Start Date** 11/04/86 **Completion Date** 03/31/88	Inactive Production Facility An abandoned chemical supply company left rooms stacked from floor to ceiling with incompatible chemicals. Many were not labeled.	Volatile Organics Metals Acids Low-Level Radioactive Waste	Direct Contact Fire/Explosion Hazard	Site Security Sampling/Analysis Overpacked Drums Disposal
Name Commercial Oil **City** Oregon **State** OH **NPL** N **Cost** $1,463,000 **Start Date** 02/01/88 **Completion Date** 06/09/88	Inactive Production Facility This closed facility contained deteriorating drums, tanks, ponds, lagoons, tanker trucks, and a contaminated landfill area.	PCBs	Direct Contact Surface Water Contamination	Pumped Contaminants Overpacked Drums Excavation Disposal AT: Physical Carbon Adsorption
Name Greiners Lagoon + **City** Fremont **State** OH **NPL** N **Cost** $519,250 **Start Date** 08/19/87 **Completion Date** 06/10/88	Inactive Waste Management Facility Ponds, created to dispose of waste oil, had a history of overflowing. The water and oil wastes were known to be contaminated.	PCBS Waste Oils	Direct Contact Groundwater Contamination Soil Contamination Surface Water Contamination	Excavation Organized Materials Solidification Disposal
Name K + S Circuits **City** Phillispburg **State** OH **NPL** N **Cost** $359,000 **Start Date** 03/28/88 **Completion Date** 07/01/88	Inactive Production Facility This facility was abandoned, leaving copper etching wastes throughout the site.	Acids Bases	Direct Contact Groundwater Contamination Soil Contamination	Sampling/Analysis Bulked Materials Site Restoration Disposal

+Note: Previous removal was completed at site. See Introduction for details.

REGION 5

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Laskin/Poplar Oil + **City** Jefferson **State** OH **NPL** Y **Cost** $4,255 **Start Date** 12/21/87 **Completion Date** 12/21/87	Inactive Waste Management Facility Liquids stored in tanks and ponds onsite contained heavy metals, PCBs, and other organics. The fence installed in an earlier action was in need of repair.	PCBs Waste Oils Metals Solvents	Direct Contact Drinking Water Contamination Surface Water Contamination	Site Security
Name Reliable Plating Co **City** Findlay **State** OH **NPL** N **Cost** $294,793 **Start Date** 03/31/88 **Completion Date** 09/19/88	Inactive Production Facility An estimated 10,000 to 12,000 gallons of processing waste were stored in deteriorating vats and drums at this defunct plating company.	Cyanides Metals Acids	Direct Contact Drinking Water Contamination Groundwater Contamination Soil Contamination	Excavation Disposal
Name Summit National Liquid + **City** Deerfield Twp. **State** OH **NPL** Y **Cost** $363,326 **Start Date** 03/26/87 **Completion Date** 05/19/88	Inactive Waste Management Facility Over 20,000 deteriorating drums and numerous bulk tanks were stored above and below ground at this site. A contaminated waste lagoon had deteriorated and overflowed.	PCBs Cyanide Volatile Organics Pesticides Waste Oils Acids Solvents	Direct Contact Drinking Water Contamination Fire/Explosion Hazard Groundwater Contamination Soil Contamination Surface Water Contamination	Pumped Contaminants Organized Materials Temporary Storage
Name Better Brite III/Chippewa **City** Chippewa **State** WI **NPL** N **Cost** $94,000 **Start Date** 05/04/87 **Completion Date** 04/01/88	Inactive Production Facility Hazardous materials were improperly stored in drums, plating tubes, pails, roll off boxes and vats at this facility. Visible soil contamination was evident.	Cyanide Metals Acids	Direct Contact	Site Security Sampling/Analysis Disposal
Name Chem Sciences **City** Germantown **State** WI **NPL** N **Cost** $387,000 **Start Date** 04/06/87 **Completion Date** 03/10/88	Inactive Production Facility The site was accessible with many scattered drums, pools of standing fluids, and stressed vegetation. Workers had dumped some drum contents onto the ground.	Acids Solvents	Direct Contact Fire/Explosion Hazard Groundwater Contamination Soil Contamination	Sampling/Analysis Organized Materials Overpacked Drums Excavation Site Restoration Disposal

+Note: Previous removal was completed at site. See Introduction for details.

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Lakewood **City** Lakewood **State** WI **NPL** N **Cost** $25,000 **Start Date** 06/27/88 **Completion Date** 07/21/88	Other This was an emergency removal action to include additional homes on a municipal water line.	Volatile Organics	Drinking Water Contamination	Provided Hookups to Water Main
Name Lubricants, Inc. **City** West Allis **State** WI **NPL** N **Cost** $12,000 **Start Date** 08/28/87 **Completion Date** 11/18/87	Inactive Waste Management Facility Numerous tanks of oil waste, some leaking acidic sludge, were on site at this closed facility. Children were known to play around the tanks.	Waste Oils Solvents	Direct Contact Fire/Explosion Hazard	Site Security Sampling/Analysis
Name Try Chem Corp **City** Milwaukee **State** WI **NPL** N **Cost** $288,600 **Start Date** 11/16/87 **Completion Date** 05/25/88	Inactive Production Facility Vats, pits and drums on site contained hazardous materials. The drums were deteriorated and vandalism had occurred.	Volatile Organics Acids Solvents	Direct Contact	Site Security Sampling/Analysis Pumped Contaminants Containment/Retention Bulked Materials Site Restoration Disposal

+Note: Previous removal was completed at site. See Introduction for details.

U. S. EPA REGION 6



For Information Contact:

Chief, Emergency Response Branch, Environmental Services Division
1445 Ross Avenue
Dallas, TX 75202
(214) 655-2270

REGION VI COMPLETIONS LISTED IN VOLUMES I AND II

ARKANSAS
Allen Transformer
Batesville Landfill Fire
Greens PCB Drums

LOUISIANA
Barge Star 7 - CG
Cleve Reber
Old Inger Oil Refinery
Stonewall Drug Dump
W. J. Oil Co.

NEW MEXICO
Argent Corporation
Cimarron Mining Site
Pronto Services
S. Valley PCB Tank Site

OKLAHOMA
10th Street Frazier Pits
Duncan Transformer Site
Haddock Airport
Jack Dennis Pesticide Burnsite
Tar Creek (Ottawa County)
Wheatland Drum

TEXAS
301 Main Street
Acrylonitril Spill
Aggie Chemical
Amoco Dock 31 - CG
Barker Chemical
Bestplate Inc.
Bio-Ecology Systems, Inc.
Cargo Ship Explosion

TEXAS (Cont)
Chemical Drums - Padre Island - CG
Crystal Chemcial Co.
Crystal City Airport
Dempsey Residence
French, Ltd.
Geneva Ind/Furhmann Energy Corp.
Heritage/Laurel
Highlands Acid Pit
Holley Residence
Houston Ship Channel
J + J Plastics
Matagorda Island - CG
Midnight Dump - CG
Motco, Inc.
Near Wills Point
Niagara Chemical
Padre & Mustang Islands 86 - CG
Padre & Mustang Islands I - CG
Padre & Mustang Islands II - CG
Padre & Mustang Islands III - CG
Padre Island IV (Leguna Madre) - CG
Panther Creek - CG
Pesses Chemical
Petro-Chemical Systems
Pirates Beach - CG
Ship Channel - CG
Sikes Disposal Pits
Skylark (Yates Residence)
South Acres
South of Waco
Stewco, Inc.
Styrene Spill - CG
Texarkana Woodpreserving
Triangle Chemical Co.
Winkler Road

REGION 6

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Mountain Pine Pressure Treating **City** Plainview **State** AR **NPL** N **Cost** $500,000 **Start Date** 12/11/87 **Completion Date** 04/13/88	Inactive Production Facility Lagoons and tanks of liquid pentachlorophenol were leaking into drinking water supplies at this closed wood treatment facility.	Dioxin Pesticides Metals	Direct Contact Drinking Water Contamination	Site Security Pumped Contaminants Solidified Materials Excavation Capping Temporary Storage Site Restoration Disposal AT: Physical-Carbon Adsorption
Name Old Henley **City** Norphlet **State** AR **NPL** N **Cost** $10,000 **Start Date** 08/18/87 **Completion Date** 12/15/87	Inactive Waste Management Facility The site consisted of 5 acidic waste oil pits, approximately 275 scattered drums, and three storage tanks. These were abandoned when the facility closed.	Waste Oils Metals	Air Contamination/Inhalation Direct Contact Soil Contamination	Site Security
Name American Creosote **City** Winnfield **State** LA **NPL** N **Cost** $148,000 **Start Date** 03/28/88 **Completion Date** 05/04/88	Inactive Production Facility The site was an abandoned facility with unlimited access and contaminated with waste oils and sludges. The facility consisted of storage tanks, a sludge pit, a lagoon, a pond, and a chemical laboratory.	Waste Oils Solvents	Air Contamination/Inhalation Direct Contact Groundwater Contamination Soil Contamination Surface Water Contamination	Sampling/Analysis
Name American Creosote + **City** Winnfield **State** LA **NPL** N **Cost** $148,000 **Start Date** 06/01/88 **Completion Date** 07/21/88	Inactive Production Facility A lagoon and pond on-site were overflowing with sludges and contaminated waste oils from the closed wood treatment plant.	Waste Oils Solvents	Air Contamination/Inhalation Direct Contact Groundwater Contamination Soil Contamination Surface Water Contamination	Pumped Contaminants Containment AT: Physical-Carbon Adsorption

+Note: Previous removal was completed at site. See Introduction for details.

REGION 6

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Old Inger Oil Refinery + **City** Darrow **State** LA **NPL** Y **Cost** $30,000 **Start Date** 08/23/88 **Completion Date** 08/26/88	Inactive Waste Management Facility Lagoons and ponds holding contaminated waste overflow were eroded and threatened to spill. A berm had deteriorated significantly.	Volatile Organics Metals Solvents	Direct Contact Soil Contamination Surface Water Contamination	Site Security Migration Control
Name South Valley/Whitfield **City** Albuquerque **State** NM **NPL** Y **Cost** $15,000 **Start Date** 03/16/88 **Completion Date** 04/26/88	Other The site was scattered with open drums of antifreeze, surficant and used motor oil from a truck cleaning operation. There were also two tank cars of sulfuric acid and tar.	Acids	Direct Contact Groundwater Contamination Soil Contamination Surface Water Contamination	Pumped Contaminants Disposal AT: Chemical Neutralization
Name Compass Ind. (Avery Drive) **City** Tulsa **State** OK **NPL** Y **Cost** $65,000 **Start Date** 05/26/88 **Completion Date** 06/29/88	Inactive Waste Management Facility The site contained hazardous industrial wastes at depths of up to 30 feet, including drums of contaminated soils.	PCBs Pesticides Waste Oils Metals Acids Solvents	Air Contamination/Inhalation Direct Contact Groundwater Contamination Soil Contamination Surface Water Contamination	Site Security Temporary Storage
Name American Thio-Chem **City** Fort Worth **State** TX **NPL** N **Cost** $1,300,000 **Start Date** 06/09/88 **Completion Date** 09/28/88	Inactive Production Facility This site was a condemned warehouse containing a pesticide formulating facility, two laboratories, assorted chemicals, pesticides, and chemicals. Vandalism had occurred.	Metals Acids Solvents	Direct Contact Fire/Explosion Hazard	Site Security Sampling/Analysis Overpacked Drums Organized Materials Site Restoration Disposal AT: Thermal Destruction
Name Best Plate, Inc. + **City** Hutchins **State** TX **NPL** N **Cost** $245,000 **Start Date** 03/09/88 **Completion Date** 05/25/88	Inactive Production Facility Highly acidic and basic compounds stored in open replating-waste vats were in danger of leaking.	Acids Bases	Direct Contact	Sampling/Analysis Organized Materials Bulked Materials Disposal

+Note: Previous removal was completed at site. See Introduction for details.

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Crystal City Airport + **City** Houston **State** TX **NPL** Y **Cost** $10,000 **Start Date** 06/01/88 **Completion Date** 06/03/88	Other Areas surrounding the hangers at this airport were contaminated with pesticides from crop dusting operations.	Pesticides	Soil Contamination	Site Security Capping
Name Jefferson Road Drum **City** Grand Praire **State** TX **NPL** N **Cost** $30,000 **Start Date** 08/11/88 **Completion Date** 08/16/88	Midnight Dump Thirty 55-gallon drums were dumped and submerged in a local creek.	Metals	Air Contamination/Inhalation Direct Contact Surface Water Contamination	Organized Materials Sampling/Analysis Disposal
Name Love Residence **City** Friendswood **State** TX **NPL** N **Cost** $1,364,527 **Start Date** 03/12/87 **Completion Date** 10/16/87	Midnight Dump A residential lawn was found to be contaminated with radioactive soil, which had been introduced as fill dirt.	Low-level Radioactive Waste	Direct Contact	Sampling/Analysis Excavation Site Restoration Disposal
Name Senuta Residence **City** Friendswood **State** TX **NPL** N **Cost** $1,039,040 **Start Date** 03/09/87 **Completion Date** 10/16/87	Midnight Dump A radiation survey overflight revealed this residential lawn to have radiation contaminated soil. This resulted from the introduction of radioactive fill dirt.	Low-level Radioactive Waste	Direct Contact	Sampling/Analysis Excavation Site Restoration Disposal
Name Sikes Disposal Pits + **City** Crosby **State** TX **NPL** Y **Cost** $182,000 **Start Date** 03/07/88 **Completion Date** 04/09/88	Inactive Waste Management Facility Five pits of unsegregrated wastes and a large number of drums were on the site of this closed facility . Children had played at the site regularly.	Solvents	Soil Contamination Surface Water Contamination	Site Security

+Note: Previous removal was completed at site. See Introduction for details.

U. S. EPA REGION 7



For Information Contact:

Chief, Emergency Planning and Response Branch,
Environmental Services Division
25 Funston Road
Kansas City, KS 66115
(913) 236-3888

REGION 7

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Eginore Fertilizer **City** Lorimor **State** IA **NPL** N **Cost** $218,300 **Start Date** 03/13/87 **Completion Date** 03/03/88	Inactive Production Facility This site consisted of four deteriorating storage buildings, five decaying above-ground storage tanks, and approximately two tons of buried chemicals.	Pesticides	Direct Contact Drinking Water Contamination	Sampling/Analysis Organized Materials Excavation Disposal
Name Cherokee County(Tri-State)+ **City** Cherokee County **State** KS **NPL** Y **Cost** $1,000 **Start Date** 10/14/87 **Completion Date** 09/20/88	Inactive Production Facility As a result of past mining practices the groundwater throughout this county was contaminated with metals. This action was to add distillation units at two additional residences.	Metals	Drinking Water Contamination	AT: Physical-Filtration/Exchange
Name Roe Lane Tank **City** Kansas City **State** KS **NPL** N **Cost** $31,400 **Start Date** 10/29/87 **Completion Date** 02/05/88	Other A 6,000-gallon tank containing plating wastes and a three-inch surface layer of sludge was abandoned on an eroded streambank. Soil contamination was evident.	Metals Solvents	Direct Contact Surface Water Contamination	Pumped Contaminants Bulked Materials Excavation Disposal
Name Baldwin Park **City** Aurora **State** MO **NPL** N **Cost** $140,000 **Start Date** 11/16/87 **Completion Date** 03/02/88	Inactive Waste Management Facility Due to dumping of filter cake wastes by a pharmaceutical company, there was widespread dioxin contamination at this abandoned dump.	Dioxin	Direct Contact Soil Contamination	Site Security Excavation Capping Site Restoration AT: Thermal Destruction
Name B & B Salvage **City** Warrensburg **State** MO **NPL** N **Cost** $1,053,350 **Start Date** 05/26/87 **Completion Date** 03/31/88	Other The facility received over 450 PCB-contaminated transformers which had not been properly neutralized. Resulting soil contamination has spread off site.	PCBs	Direct Contact Soil Contamination	Site Security Excavation Site Restoration Disposal AT: Recycling

+Note: Previous removal was completed at site. See Introduction for details.

REGION 7

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Broadway Salvage Oil #1 **City** St. Louis **State** MO **NPL** N **Cost** $205,710 **Start Date** 11/16/87 **Completion Date** 02/16/88	Midnight Dump Unknown persons dumped PCB-contaminated oil from seven transformer casings causing widespread soil contamination.	PCBs	Direct Conact Soil Contamination	Sampling/Analysis Excavation Site Restoration Disposal
Name Castlewood Community Site + **City** St. Louis **State** MO **NPL** N **Cost** $8,630,565 **Start Date** 07/01/85 **Completion Date** 05/20/88	Other Waste oil contaminated with TCDD (Dioxin) was sprayed over a dirt/gravel road, exposing residential, commercial, and public properties.	Dioxin	Direct Contact Soil Contamination	Excavation Temporary Relocation Temporary Storage
Name Crooked River Drums **City** Ray County **State** MO **NPL** N **Cost** $2,000 **Start Date** 09/02/88 **Completion Date** 09/02/88	Midnight Dump Four unmarked drums were discovered abandoned between an unpaved road and the bank of a river.	Solvents	Direct Contact Soil Contamination Surface Water Contamination	Sampling/Analysis Pumped Contaminants Disposal
Name Delmar Street Drums **City** St. Louis **State** MO **NPL** N **Cost** $342,227 **Start Date** 06/22/87 **Completion Date** 06/02/88	Midnight Dump Leaking 55-gallon drums were discovered during an excavation in a residential area. Further analysis revealed 287 drums containing flammable paint wastes and potential heavy metal contamination.	Metals Solvents	Direct Contact Fire/Explosion Hazard Soil Contamination	Sampling/Analysis Overpacked Drums Disposal AT: Thermal Destruction
Name Dickhoener PCB Site **City** Cuba **State** MO **NPL** N **Cost** $21,600 **Start Date** 04/18/88 **Completion Date** 06/01/88	Other Several drums and cans of PCB-contaminated oil and filter material were found stored in a rural residential shed.	PCBs	Direct Contact Soil Contamination	Sampling/Analysis Overpacked Drums Excavation Disposal

+Note: Previous removal was completed at site. See Introduction for details.

REGION 7

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Jackson St. Drums **City** Kansas City **State** MO **NPL** N **Cost** $5,000 **Start Date** 07/19/88 **Completion Date** 07/19/88	Midnight Dump Ten drums of unknown materials were dumped on an abandoned lot in a residential downtown neighborhood.	Volatile Organics	Direct Contact Fire/Explosion Hazard Soil Contamination	Organized Materials Disposal
Name Minker/Stout/Romaine Creek **City** Imperial **State** MO **NPL** Y **Cost** $3,372,525 **Start Date** 05/30/83 **Completion Date** 10/11/87	Midnight Dump Dioxin-contaminated fill was deposited on residences near the Minker residence. Concentrations of dioxin reached 348 parts per billion.	Dioxin	Direct Contact Soil Contamination	Site Security Sampling/Analysis Excavation Temporary Relocation Migration Control Temporary Storage
Name Odessa Manufacturing Co. **City** Maysville **State** MO **NPL** N **Cost** $4,000 **Start Date** 09/02/88 **Completion Date** 09/02/88	Inactive Production Facility Three drums of flammable solvent liquids were abandoned at a former manufacturing facility.	Solvents	Fire/Explosion Hazard	AT: Recycling
Name Quail Run Mobile Manor **City** Gray Summit **State** MO **NPL** Y **Cost** $9,166,524 **Start Date** 05/16/83 **Completion Date** 12/15/87	Other Dioxin contamination was discovered on roads, roadsides, yards, and in at least one mobile home interior at a trailer park containing 32 occupied units.	Dioxin	Direct Contact Soil Contamination	Temporary Relocation Excavation Site Restoration Temporary Storage
Name Robert Street Drums **City** Kansas City **State** MO **NPL** N **Cost** $11,850 **Start Date** 09/02/88 **Completion Date** 09/02/88	Midnight Dump Five drums of extremely volatile solvents were abandoned in a storage shed on a residential rental property. Summer heat caused the bung seals on two of them to burst.	Solvents	Direct Contact Fire/Explosion Hazard	Temporary Storage Disposal

+Note: Previous removal was completed at site. See Introduction for details.

REGION 7

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Store Safe Explosives **City** Kansas City **State** MO **NPL** N **Cost** $50,000 **Start Date** 04/23/88 **Completion Date** 08/09/88	Other EPA assistance was requested to remove illegally stored explosives and reactive chemicals from a rental storage facility.	Volatile Organics	Fire/Explosion Hazard	Organized Materials Disposal Detonation
Name Hoffman Drums **City** Alliance **State** NE **NPL** N **Cost** $15,000 **Start Date** 10/05/87 **Completion Date** 12/07/87	Other A drum recycler passed away, leaving his widow with seven deteriorating drums containing trichloroethylene.	Volatile Organics	Direct Contact Air Contamination/Inhalation	Overpacked Drums Disposal

+Note: Previous removal was completed at site. See Introduction for details.

U. S. EPA REGION 8



For Information Contact:

Chief, Emergency Response Branch, Waste Management Division
One Denver Place
999 18th Street, Suite 500
Denver, CO 80202-2405
(303) 293-1723

REGION VIII COMPLETIONS LISTED IN VOLUMES I AND II

COLORADO
California Gulch - Maestes Well
Camax Site
Denver Radium - B&C Metals
Eagle Mine
Frejonley
Gene Murren
Herold Site (Black Hawk)
PDC Spas
Woodbury Chemical Co.

MONTANA
Motherlode Facility

NORTH DAKOTA
Arsenic Trioxide
Grand Forks Drum Site
Vaagan-Dahle Farm

SOUTH DAKOTA
Heldt Chemical (SD Services)

UTAH
Green River Cyanide
Montgomery Ward Store
Randall Residence

WYOMING
Ellerby Refining Site
Truck Accident

REGION 8

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Captain Jack Mill **City** Ward **State** CO **NPL** N **Cost** $9,000 **Start Date** 12/08/87 **Completion Date** 01/28/88	Other Fifteen deteriorating drums, some of them open, were located on a mill and mine site. They were suspected of containing sulfuric acid and unknown organics.	Volatile Organics Acids	Direct Contact Surface Water Contamination	Pumped Contaminants Disposal
Name Englewood DDT **City** Englewood **State** CO **NPL** N **Cost** $7,000 **Start Date** 05/01/87 **Completion Date** 10/21/87	Midnight Dump One-hundred and fifty pounds of DDT powder and containers of other pesticides were deserted in a garden shed. The area was unsecured and considerable spillage had occurred.	Pesticides	Direct Contact Air Contamination/Inhalation	Bulked Materials AT: Thermal Destruction
Name Farmers Irrigation Ditch **City** Broomfield **State** CO **NPL** N **Cost** $25,000 **Start Date** 04/30/87 **Completion Date** 01/28/88	Midnight Dump Nine 55-gallon drums of fiberized aluminum were dumped illegally in an irrigation ditch.	Asbestos Toxic Gases Solvents Metals	Direct Contact Food Chain Contamination Soil Contamination Surface Water Contamination	Sampling/Analysis Organized Materials Excavation Disposal
Name Graff Drums **City** Ft. Morgan **State** CO **NPL** N **Cost** $52,529 **Start Date** 06/30/87 **Completion Date** 01/20/88	Midnight Dump Thirty-seven drums of liquid plating wastes and six vats of solid residues were dumped in a construction storage yard. Three other drums from the same source were abandoned in a nearby trailer park.	Cyanide Acids	Air Contamination/Inhalation Direct Contact Soil Contamination Surface Water Contamination	Sampling/Analysis Organized Materials Disposal
Name High Qualtiy Circuits **City** Colorado Springs **State** CO **NPL** N **Cost** $74,700 **Start Date** 09/21/87 **Completion Date** 03/29/88	Inactive Production Facility Approximately 74 drums were abandoned in an industrial area by a local plating facility.	Cyanides Metals Acids	Air Contamination/Inhalation Direct Contact Surface Water Contamination	Sampling/Analysis Organized Materials Disposal

+Note: Previous removal was completed at site. See Introduction for details.

REGION 8

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Mule Creek Drums **City** Adams County **State** CO **NPL** N **Cost** $8,762 **Start Date** 06/30/87 **Completion Date** 11/13/87	Midnight Dump Thirty-four drums were found dumped in a creek bed.	Volatile Organics Solvents	Air Contamination/Inhalation Direct Contact Fire/Explosion Hazard Surface Water Contamination	Organized Materials Sampling/Analysis AT: Recycling
Name Riverside Cemetery Drums **City** Commerce City **State** CO **NPL** N **Cost** $12,000 **Start Date** 05/31/88 **Completion Date** 07/13/88	Midnight Dump Twelve to fourteen drums were discovered adjacent to a canal along a bike trail. Vandals had foiled local efforts to fence in the drums.	Volatile Organics	Direct Contact Fire/Explosion Hazard Surface Water Contamination	Organized Materials Disposal
Name Rocky Mtn Custom Chrome **City** Colorado Springs **State** CO **NPL** N **Cost** $88,000 **Start Date** 08/27/87 **Completion Date** 03/08/88	Inactive Production Facility Approximately 20 open or leaking containers of plating solution were found abandoned onsite.	Metals Acids Cyanides	Direct Contact Soil Contamination Air Contamination/Inhalation	Site Security Overpacked Drums Sampling/Analysis Disposal
Name South Adams County Water and Sanitation District **City** Denver **State** CO **NPL** N **Cost** $2,933,904 **Start Date** 06/11/86 **Completion Date** 09/30/88	Other Public and private wells tapped a shallow aquifer contaminated with trichloroethylene.	Solvents	Air Contamination/Inhalation Drinking Water Contamination	Provided Hookups to Water Main AT: Physical-Carbon Adsorption

+Note: Previous removal was completed at site. See Introduction for details.

REGION 8

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Mill Creek Site (Anaconda) **City** Anaconda **State** MT **NPL** Y **Cost** $0 **Start Date** 07/15/86 **Completion Date** 09/13/88	Other Huge quantities of tailings and granulated slag caused widespread soil contamination.	Metals	Air Contamination/Inhalation Direct Contact	Temporary Relocation
Name Reliance Refining Co. **City** Kalispell **State** MT **NPL** N **Cost** $40,470 **Start Date** 05/19/88 **Completion Date** 05/27/88	Inactive Production Facility Large pools of PCP-contaminated sludge at an abandoned oil refinery were openly accessible and incurred some off-site seepage.	PCPs	Direct Contact	Site Security
Name Silver Bow Creek/Walkerville **City** Butte **State** MT **NPL** Y **Cost** $722,250 **Start Date** 02/09/88 **Completion Date** 09/30/88	Other Elevated levels of metals were found adjacent to and migrating into residential areas. The contamination stemmed from tailings piles, once used in mining and milling operations.	Metals	Air Contamination/Inhalation Direct Contact	Site Security Excavation Containment
Name Wasatch Chemical Co. (Lot 6) **City** Salt Lake City **State** UT **NPL** Y **Cost** $159,136 **Start Date** 03/19/86 **Completion Date** 06/30/88	Active Production Facility Forty-eight 55-gallon drums, many small containers and carboys, and 13 deteriorated gas cylinders were left onsite. Several of the drums were leaking.	Dioxin Pesticides Toxic Gases Acids Solvents	Air Contamination/Inhalation Direct Contact Fire/Explosion Hazard Groundwater Contamination	Sampling/Analysis Temporary Storage Detonation

+Note: Previous removal was completed at site. See Introduction for details.

REGION 8

Superfund Emergency Response Actions

Site Information		Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name	Buffalo Fire	Active Waste Management Facility A fire at a barrel refurbishing facility caused a release of waste chemicals in the firefighting water, which was contained in a dirt irrigation ditch.	Volatile Organics Solvents	Direct Contact Groundwater Contamination Surface Water Contamination	Pumped Contaminants Organized Materials Disposal
City	Buffalo				
State	WY				
NPL	N				
Cost	$1,059				
Start Date	01/27/88				
Completion Date	01/28/88				

+Note: Previous removal was completed at site. See Introduction for details.

U. S. EPA REGION 9

ALSO: AS
GU
TT

For Information Contact:

Chief, Emergency Response Section, Field Operations Branch, Toxic and Waste Management Division
215 Freemont Street
San Francisco, CA 94105
(415) 974-7466

REGION IX COMPLETIONS LISTED IN VOLUMES I AND II

AMERICAN SAMOA
ASPA Power Plant
Satala Power Plant
Tafuna Power Plant
Taputimu Farm

ARIZONA
Dela - Tek
Gila River Indian Reservation
The Chrome Shop
Tuba City Acid Tank

CALIFORNIA
Abandoned Drum - CG
Aero Quality Plating Co.
Angeles National Forest
Arnold Weed Control Site
Bloomfield Avenue
Brown's Field Site
California Bionuclear
California Creative Dynamics
Cherokee Trucking
Copperopolis Site
Crystal Cove Beach - CG
Dixco Chemical Sales
Drainage Ditch
E.C. Kramer
El Monte Site
Floating Drum - CG
Garden Valley Site
Garvey Avenue Site
General Disposal
L. Fricker Co.
Laguna Beach II - CG
Long Beach Drum - CG
McColl
N. Tulip St. - Escondido
Nickel Solution Recycling
Norwalk Drum Site
Operating Industries
Parkside Drive
Purity Oil Sales, Inc.
Rigel Street
ROIC - Sun Valley

CALIFORNIA (Cont.)
Sacramento River - CG
South Bay Asbestos Area
South Half Moon Bay - CG
Standard Chemical Co.
Stringfellow Acid Pits
Tecate Site
Unknown Chemical Drums - CG
Western States Refining
Yucaipa Drug Lab

HAWAII
Hauula Beach Park - CG
F/V Victoria II Keehi Lagoon
PCB Transformers - CG
Pier 35 - CG

NEVADA
Big Spring Ranch
Cyanide Spill
Echo Bay Station
Washoe Drum

TRUST TERRITORIES
PCB Wastes (1 - University of Guam)
PCB Wastes (11 - Harmon)
PCB Wastes (13 - GPA/ Naval Station)
PCB Wastes (14 - CNMI PCB)
PCB Wastes (15 - Saipan)
PCB Wastes (16 - Palau)
PCB Wastes (17 - Marshall Island)
PCB Wastes (18 - Guam Dept. of Public Health)
PCB Wastes (19 - Marshall Island)
PCB Wastes (2 - University of Guam)
PCB Wastes (20 - Marshall Island)
PCB Wastes (21 - Ebeye Pub)
PCB Wastes (25 - Ponape Elect)
PCB Wastes (26 - Ponape

TRUST TERRITORIES (Cont.)
PCB Wastes (27 - Ponape DPFOR)
PCB Wastes (28 - Ponape)
PCB Wastes (29 - Kosrae)
PCB Wastes (3 - Guam Memorial Hospital)
PCB Wastes (30 - Truk)
PCB Wastes (32 - Yap)

PCB Wastes (33 - Yap)
PCB Wastes (4 - Guam Public Hospital)
PCB Wastes (5 - Guam Dept. of Agriculture)
PCB Wastes (7- Guam Dept. of Economics)
PCB Wastes (8- Guam Phys.)
PCB Wastes (9 - Guam PHL)
PCB Wastes (A - Guam Dept. of Education)
PCB Wastes (B - Dela Cruz
PCB Wastes (C - Majuro Hospital)
PCB Wastes (D - Medical Clinic)
PCB Wastes (F - Prot Yap)
PCB Wastes (G - USCG Loran)

REGION 9

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Gila River Site #2 **City** Maricopa **State** AZ **NPL** N **Cost** $30,000 **Start Date** 01/17/88 **Completion Date** 05/09/88	Midnight Dump Six drums containing suspected pesticides/herbicides were abandoned on the site.	Pesticides	Direct Contact	Overpacked Drums Excavation Disposal
Name Stanford Site #1 **City** Yuma **State** AZ **NPL** N **Cost** $101,000 **Start Date** 03/20/87 **Completion Date** 11/05/87	Other Approximately 1.5 acres of land were used for storage of farm equipment and pesticides which had leaked and spilled on surrounding soil.	Pesticides	Direct Contact Soil Contamination	Site Security AT: Physical-Carbon Adsorption AT: Biological Biodegradation
Name Stanford Site #2 **City** Yuma **State** AZ **NPL** N **Cost** $173,000 **Start Date** 03/20/87 **Completion Date** 11/05/87	Other An abandoned trailer contained approximately 90 chemical containers, some of them leaking. There was evidence of buriedof pesticides and vandalism.	Pesticides	Direct Contact Soil Contamination	Site Security Sampling/Analysis Excavation Disposal
Name Abco Metal Finishing **City** Monrovia **State** CA **NPL** N **Cost** $440,000 **Start Date** 05/06/87 **Completion Date** 11/17/87	Inactive Production Facility The site contained approximately 36 open topped vats and 250 55-gallon drums. Cyanide and acid solutions had been spilled and hydrogen gas was detected in the air.	Cyanide Acids Bases	Air Contamination/Inhalation Direct Contact Soil Contamination	Sampling/Analysis Temporary Relocation Pumped Contaminants Organized Materials Solidified Materials Excavation Disposal
Name Builders Hardware Finishing **City** Los Angeles **State** CA **NPL** N **Cost** $405,000 **Start Date** 05/23/88 **Completion Date** 07/15/88	Active Production Facility A fire damaged a metal plating shop housing containers of acids, bases, cyanides, oxidizers, and degreasing solvents. The threat of release of cyanide gas was serious, and resulted in the precautionary evacuation of 11,000 people.	Cyanide Acids Bases Solvents	Air Contamination/Inhalation Direct Contact Surface Water Contamination	Site Security Temporary Evacuation of Population Sampling/Analysis Organized Materials Disposal

+Note: Previous removal was completed at site. See Introduction for details.

REGION 9

Superfund Emergency Response Actions

Site Information		Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name	Del Norte Pesticide Storage	Inactive Waste Management Facility This one-acre site was used as a county-wide collection point for storage and disposal of pesticide and herbicide containers, many of them partially full.	Pesticides	Groundwater Contamination Soil Contamination Surface Water Contamination Ecological Damage	Sampling/Analysis Excavation Site Restoration Disposal
City	Crescent City				
State	CA				
NPL	Y				
Cost	$255,000				
Start Date	08/24/87				
Completion Date	02/28/88				
Name	Industrial Waste Processing	Inactive Waste Management Facility Approximately 250 55-gallon drums of waste solvents and lead solder flux, 50 cubic yards of lead solder waste, and 50 50-pound fiber bags and 30 55-gallon drums of asbestos were on site.	Asbestos Metals Solvents	Air Contamination/Inhalation Direct Contact Drinking Water Contamination Fire/Explosion Hazard Soil Contamination	Site Security Sampling/Analysis Organized Materials Overpacked Drums Bulked Materials Disposal
City	Fresno				
State	CA				
NPL	N				
Cost	$673,877				
Start Date	06/20/88				
Completion Date	08/18/88				
Name	Lorentz Barrel & Drum	Inactive Waste Management Facility The soil and aquifer below this site had been contaminated by a wide variety of hazardous materials. Forty thousand mostly empty, and 800 full drums of waste were onsite.	PCBs Pesticides Metals Solvents	Direct Contact Fire/Explosion Hazard Groundwater Contamination Soil Contamination	Sampling/Analysis Organized Materials Neutralized Materials Disposal
City	San Jose				
State	CA				
NPL	Y				
Cost	$757,000				
Start Date	09/08/87				
Completion Date	03/29/88				
Name	McColl +	Inactive Waste Management Facility In an earlier action, the site was capped to contain over 250,000 tons of waste and contaminated soil. Seeps and odors were discovered migrating off site from under the cap.	Waste Oils Acids	Air Contamination/Inhalation Direct Contact	Excavation Disposal
City	Fullerton				
State	CA				
NPL	Y				
Cost	$244,000				
Start Date	01/25/88				
Completion Date	03/31/88				
Name	McKinnon	Midnight Dump Twenty deteriorated drums suspected of containing hazardous waste were found in an abandoned van.	Volatile Organics Solvents	Air Contamination/Inhalation Direct Contact Fire/Explosion Hazard	Sampling/Analysis Overpacked Drums Disposal AT: Recycling AT: Thermal Destruction
City	San Francisco				
State	CA				
NPL	N				
Cost	$40,000				
Start Date	11/05/87				
Completion Date	12/29/87				

+Note: Removal was completed at site. See Introduction for details.

REGION 9

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Ryan Paints **City** Oakland **State** CA **NPL** N **Cost** $96,124 **Start Date** 02/05/88 **Completion Date** 03/14/88	Inactive Waste Managment Facility This site was accessible to pedestrians and contained approximately 250 drums of paint wastes, many of them deteriorated.	Volatile Organics Solvents	Air Contamination/Inhalation Direct Contact Fire/Explosion Hazard	Sampling/Analysis Excavation Site Restoration Disposal AT: Recycling AT: Thermal Destruction
Name Waste Disposal Inc. **City** Los Angelos **State** CA **NPL** Y **Cost** $18,000 **Start Date** 03/28/88 **Completion Date** 04/27/88	Inactive Waste Management Facility The site was once used for industrial disposal and had a waste pond which was then filled in. The property was open to traffic that stirred up contaminated dust.	Unknown	Direct Contact Soil Contamination	Site Security
Name Whittier Propel **City** Whittier **State** CA **NPL** N **Cost** $530,957 **Start Date** 02/22/88 **Completion Date** 04/06/88	Inactive Production Facility A car fuel additive, "Propel", was stored on site ever since the company closed. The containers were leaking and deteriorating, causing some migration.	Volatile Organics	Direct Contact Fire/Explosion Hazard Groundwater Contamination Soil Contamination Surface Water Contamination	Overpacked Drums Site Restoration AT: Thermal Destruction
Name Aerolite Chrome **City** Reno **State** NV **NPL** N **Cost** $290,000 **Start Date** 03/18/88 **Completion Date** 04/10/88	Inactive Production Facility The site inventory included 25 open topped vats, 100 55-gallon drums and various containers containing 10,000 gallons and 2,000 pounds of chemicals and wastes.	Cyanide Volatile Organics Metals Acids Bases Solvents	Air Contamination/Inhalation Direct Contact Fire/Explosion Hazard	Site Security Sampling/Analysis Organized Materials Bulked Materials Disposal AT: Recycling
Name Poly-Carb **City** Wells **State** NV **NPL** N **Cost** $475,000 **Start Date** 06/22/87 **Completion Date** 08/15/88	Inactive Waste Management Facility Between 7,200 and 9,000 gallons of a phenol and cresol solution were spilled, contaminating approximately 1,500 cubic yards of soil. Previous cleanup efforts by the facility had failed.	Solvents	Groundwater Contamination Soil Contamination	Excavation AT: Physical Carbon Adsorption AT: Soil Leaching AT: Thermal Destruction

+Note: Previous removal was completed at site. See Introduction for details.

Superfund Emergency Response Actions

Site Information		Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name	Silverado Leach Mill	Inactive Production Facility	Cyanide	Air Contamination/Inhalation	Sampling/Analysis
City	Eureka	The site included structures that housed	Volatile Organics	Direct Contact	Neutralize Materials
State	NV	incompatable hazardous substances in	Acids	Fire/Explosion Hazard	Overpacked Drums
NPL	N	deteriorating containers. An on-site pond was		Groundwater Contamination	Disposal
Cost	$34,045	also contaminated with cyanide solutions.		Soil Contamination	
Start Date	02/02/88				
Completion Date	02/08/88				

+Note: Previous removal was completed at site. See Introduction for details.

U. S. EPA REGION 10



For Information Contact:

Chief, Superfund Response and Investigations Section,
Hazardous Waste Division
1200 Sixth Avenue
Seattle, WA 98101
(206) 442-1196

REGION X COMPLETIONS LISTED IN VOLUMES I AND II

ALASKA
Bendle's Road Oiling Co.
Ohlson Mountain PCB Site

IDAHO
Arrcom (Drexler Enterprises)
Bunker Hill Mining and Metallurgy
Comeback Mine
Emmitt PCB
Municipal Landfill
Pacific Hide & Fur Recycling

OREGON
Northwest Dust Control
Union Ave. PCB Site
United Chrome Products Inc.
Williamette River - CG

WASHINGTON
Abandoned Drum
American Surplus
Lake Washington Ship Channel - CG
Little League Pesticide
Marrowstone Island - CG
Northwest Transformer
Olympia Pesticide Fire
PCB Contamination
Spokane Drum Fire
Western Processing Co., Inc.
Williams & Son

REGION 10

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Alaska Huskey Battery **City** Anchorage **State** AK **NPL** N **Cost** $930,000 **Start Date** 06/30/88 **Completion Date** 09/09/88	Active Production Facility Years of recycling and battery production resulted in PCB and lead contamination of the soil at this facility.	PCBs Metals	Air Contamination/Inhalation Direct Contact Groundwater Contamination	Site Security Sampling/Analysis Excavation Disposal
Name U.S. DOT-Standard Steel **City** Anchorage **State** AK **NPL** Y **Cost** $1,636,508 **Start Date** 06/02/86 **Completion Date** 09/15/88	Active Production Facility A 6-acre recycling operation contained an estimated 180 PCB transformers, 500-1000 drums and containers of hazardous waste, and some 20,000 acid/lead batteries.	Dioxin PCBs Asbestos Volatile Organics Metals Solvents	Direct Contact Food Chain Contamination Groundwater Contamination Soil Contamination Surface Water Contamination	Site Security Sampling/Analysis Organize Materials Pumped Contaminants Migration Control Overpacked Drums Containment/Retention Disposal AT: Thermal Destruction AT: Recycling
Name Arrcom Corp (Drexler)+ **City** Rathdrum **State** ID **NPL** Y **Cost** $990,000 **Start Date** 05/01/87 **Completion Date** 03/01/88	Inactive Production Facility This site is located above the sole-source aquifer for 350,000 people. The site had 27 partially filled storage tanks, many of them leaking.	PCBs Asbestos Waste Oils Solvents	Direct Contact Drinking Water Contamination Groundwater Contamination Soil Contamination	Sampling/Analysis Containment/Retention Organized Materials Disposal
Name Elk River-Mitchell Site **City** Elk River **State** ID **NPL** N **Cost** $118,000 **Start Date** 09/19/88 **Completion Date** 09/24/88	Midnight Dump An illicit gold ore mercury extraction operation conducted at a residential property resulted in the contamination of a street, storm drain, culvert, ditch, and vegetation for more than five blocks.	Metals	Air Contamination/Inhalation Direct Contact Food Chain Contamination Groundwater Contamination Soil Contamination Surface Water Contamination	Sampling/Analysis Excavation Disposal

+ Note: Previous removal was completed at site. See Information for details.

Superfund Emergency Response Actions

Site Information	Incident Category/Description	Primary Contaminants	Threat(s)	Mitigative Action(s)
Name Greenspeed Pest & Lawn Management **City** Boise **State** ID **NPL** N **Cost** $295,000 **Start Date** 08/05/87 **Completion Date** 03/18/88	Inactive Production Facility Approximately 50 gallons of pesticides were spilled on a residential lot. Soil was contaminated and pesticide products and containers remained onsite.	Pesticides	Direct Contact Drinking Water Contamination Groundwater Contamination	Site Security Sampling/Analysis Disposal
Name Depoe Bay (CG) **City** Lincoln City **State** OR **NPL** N **Cost** $1,788 **Start Date** 04/25/88 **Completion Date** 07/01/88	Other A 55-gallon drum washed ashore on the beach.	PCBs Volatile Organics Waste Oils Solvents	Direct Contact	Sampling/Analysis Organized Materials Disposal
Name Lake Washington Drum (CG) **City** Seattle **State** WA **NPL** N **Cost** $2,000 **Start Date** 08/26/87 **Completion Date** 10/07/87	Other A 55-gallon drum containing trichloroethylene was found in Lake Washington.	Solvents	Direct Contact Ecological Damage Soil Contamination Surface Water Contamination	Sampling/Analysis Disposal
Name Pallister Paint Site **City** Everett **State** WA **NPL** N **Cost** $1,653,066 **Start Date** 08/19/85 **Completion Date** 02/15/88	Inactive Production Facility This was a site of uncontrolled storage of large quantities of flammable paints, military and industrial chemicals, transformer liquids, and other hazardous chemicals and compounds.	PCBs Asbestos Metals Solvents	Air Contamination/Inhalation Direct Contact Fire/Explosion Hazard Soil Contamination	Site Security Sampling/Analysis Excavation Organized Materials Overpacked Drums Disposal

+ Note: Previous removal was completed at site. See Information for details.

INDEX

SITE	REGION
#7 Commercial Street	I
10th Street Frazier Pits	VI
301 Main Street	VI
A - Chemical	V
A&F Materials Reclaiming	V
A.L. Taylor (Valley of the Drums)	IV
Abandoned Drum - CG	IV
Abandoned Drum - CG	IX
Abandoned Drum - CG	I
Abandoned Drum - CG	V
Abandoned Drum	II
Abandoned Drum Site	IV
Abandoned Drum	V
Abandoned Drum	X
Abandoned Drum/Hillsborough - CG	IV
Abandoned Drum/Marathon - CG	IV
Abandoned Drums - Ecorse	V
Abandoned Drums - Erie Canal - CG	II
Abco Metal Finishing	IX
ABM Eddystone	III
Acrylonitril Spill	VI
Aero Quality Plating Co.	IX
Aerolite Chrome	IX
Aeroquip/Republic Hose	V
Aggie Chemical	VI

SITE	REGION
Ahoskie Midnight Dump	IV
Aidex Corp.	VII
Alandale Dr. Chemical Site	[illegible]
Alaska Huskey Battery	X
Album Incinerator	V
Allen Transformer	VI
Ambler Asbestos Piles	III
American Creosote	VI
American Creosote Works (MS)	IV
American Creosote/Jackson Plant	IV
American Creosote/Pensacola	IV
American Insulator Co.	III
American Steel Drum	V
American Street Tannery	III
American Surplus	X
American Thermostat	II
American Thio - Chem	VI
Amoco Dock 31- CG	VI
Anaconda Road Site	V
Androscoggin Rivers	I
Angeles National Forest	IX
Apache Waste Oil	III
Argent Corporation	VI
Arlington Blending	IV
Army Creek Landfill	III
Arnold Weed Control Site	IX

SITE	REGION
Arrcom (Drexler Enterprises)	X
Arsenic Mines	II
Arsenic Trioxide	VIII
Asbestos Bags	V
Asbestos Dumping	II
Asbestos/Torrey Place	II
Ashland Chemical	III
ASPA Power Plant	IX
Atlantic Avenue	III
Atlantic Resources	II
Atwell Mountain Drum Site	III
Auburn Church Road Drums	IV
Auburn Road	I
Autocrat Corp.	V
B & B Salvage	VII
Babb Drums	IV
Baird & McGuire	I
Baldwin Park	VII
Baltimore Iron & Metals - CG	III
Bank County Drum	IV
Barge Star 7 - CG	VI
Barker Chemical	VI
Barnes Mill Drum Site	IV
Barnes Property	IV
Barrow County Drum Site	IV
Batesville Landfill Fire	VI

SITE	REGION
Bayshore	II
Beach Containers - CG	IV
Beach Contamination	II
Beached Drum - CG	IV
Beal Street Drum	I
Beauty Rose Chemical	VII
Belvidere Municipal Landfill	V
Bendle's Road Oiling Co.	X
Bennett Stone Quarry	V
Bensalem Drum	III
Bent Creek/James River	III
Benton Furniture Co.	IV
Bergeron Marine	IV
Berks Sand Pit - Van Ellswyck	III
Berlin & Farro	V
Bern Metals	II
Berncolor Inc. - CG	II
Berrien Products	IV
Bestplate Inc.	VI
Better Brite III / Chippewa	V
Better Brite-Chrome	V
BFG Electroplating	III
Biedler Road	III
Big John's Salvage - Hoult Road	III
Big John's Salvage	III
Big Spring Ranch	IX

SITE	REGION
Bio-Ecology Systems, Inc.	VI
Bittle Well Contamination	III
Bliss/Frontenac	VII
Bloomfield Avenue	IX
Blooming Grove	II
Bloomington Capacitor Site	V
Blue Cyanide Chips	V
Blue Poly Drum - CG	II
Blue River Flood	VII
Blue Spruce International	II
Bostic Drum	IV
Bourdeaudhui	I
Bow Chemical	V
Bowling Green Toxics	IV
Boyertown Scrap Metal	III
Brady Metals	II
Breakneck Road	I
Bridgeport Rental & Oil Services	II
Broadway Salvage Oil #1	VII
Brodhead Creek	III
Brown's Battery Breaking	III
Brown's Field Site	IX
Bruin Lagoon	III
Buckhorn Pesticide Fire	IV
Buckhorn Rd. Drum Site	IV
Buffalo Fire	VIII

SITE	REGION
Buford Highway	IV
Builders Hardware Finishing	IX
Bunker Hill Mining & Metallurgy	X
Buried Drum Removal	III
Burkett Cylinder	IV
Burns Hill Road	I
Burnt Fly Bog	II
Bursey Asbestos	I
Bush Brothers Plating	IV
Butler Tunnel	III
Byron/Johnson Salvage Yard	V
Byron Barrel & Drum	II
C & R Battery Co. Inc.	III
C&F Chemical	II
C-Way	V
C.D. Buff	IV
C.E. Brubaker	III
Caldwell County	IV
California Bionuclear	IX
California Creative Dynamics	IX
California Gulch-Maestes Well	VIII
California MD Drum	III
Callahan Drum	V
Camax Site	VIII
Camp Run Drum	III
Camplain Road	II

SITE	REGION
Camuy River Dump Site	II
Cannelton Industries	V
Cannon Engineering Corp. (CEC)	I
Cannon Engineering Corporation	I
Canton Plating & Bumper Works	IV
Cantu Well	V
Cape Cod Canal - CG	I
Cape Fear Wood Preserving	IV
Cape Hatteras National Seashore - CG	IV
Capitol Assay Labs	III
Captain Jack Mill	VIII
Cargo Ship Explosion	VI
Carolawn, Inc.	IV
Carolina Production	IV
Carolina Transformer	IV
Carter Industrial	V
Cascade Road	IV
Cashel Property	VIII
Castle Hill - CG	I
Catoosa County Labpack	IV
Caustic Chemical	IV
Caustic Midnight Dump	III
Cayadutta Creek	II
Cecil County Dump	III
Central Waste Landfill	V
Charles George Reclamation Landfill	I

SITE	REGION
Chatham Beach - CG	I
Chem Pac	V
Chem Sciences	V
Chem-Dyne	V
Chemco	V
Chemical Control	II
Chemical Drum - CG	V
Chemical Drums - Padre Island - CG	VI
Chemical Insecticide Corp.	II
Chemical Leaman Tank Lines	II
Chemical Metals Industries	III
Chemical Minerals Reclamation	V
Chemtronics, Inc.	IV
Chenault Rectifiers	IV
Cherokee Trucking	IX
Chesapeake Bay - CG	III
Chesapeake PCB Site	III
Chesterfield Tank	VII
Chicago Drum	V
Church of God Property	IV
Cimarron Mining Site	VI
City Industries Inc.	IV
Clark Property	III
Clayton Ballfield Pesticide	IV
Cleve Reber	VI
Cleveland Co. Drum	IV

SITE	REGION
Clothier Disposal	II
Coal Branch Hollow	IV
Cobb County Drum	IV
Coleman-Evans Wood Pres. Co.	IV
Colter Street	II
Columbia Park Drum	III
Comeback Mine	X
Commercial Oil	V
Community Christian Church	VII
Compass Industries (Avery Dr.)	VI
Connecticut River Drum Site	I
Cooks Landfill	I
Coons Run	III
Cooper River - CG	II
Copperopolis Site	IX
Cornell - Dublier Electronics	IV
Cottage Street	I
Cowart Vacation Bible School	IV
Creosote Tanks Release (Talleyrand)	IV
Crooked River Drums	VII
Crystal Chemical Co.	VI
Crystal City Airport	VI
Crystal Cove Beach - CG	IX
Cummings Landfill	III
Curtis Animal Products	VII
Cyanide Incident	V

SITE	REGION
Cyanide Spill	IX
Cyanide Treatment	I
Dade County Drum	IV
Danville Plating	V
Davenport Creosote Spill	IV
Davis Farm	IV
Davis Liquid Waste	I
Dead Creek	V
Dean Street (Norwood PCBs)	I
Dearborn Drums	VII
Del Norte Pesticide Storage	IX
Dela-Tek	IX
Delancy Trailer	II
Delaware Bay Drum - CG	III
Delaware River - CG	II
Delaware River II - CG	III
Delaware Sand & Gravel Landfill	III
Delmar Street Drums	VII
Dempsey Residence	VI
Denver Radium - B&C Metals	VIII
Depoe Bay - CG	X
Dickerson Post Treating	IV
Dickhoener PCB Site	VII
Distler Brickyard	IV
Distler Farm	IV
Dixco Chemical Sales	IX

SITE	REGION
Dockery Property	IV
Donaldson Roadside Spill	IV
Donegal Twp Midnight Drum	III
Dorado Drum Site	II
Dorney Road Landfill	III
DOT Maintenance Yard	IV
Dover Air Force Base	III
Dowden Landfill	V
Dracup Warehouse	III
Drainage Ditch	IX
Drake Chemical	III
Dreyfus Street	IV
Drums on Beach - CG	V
Duane Marine	II
Duell and Gardner Landfill	V
Duncan Transformer Site	VI
Duncansville Tanker	III
Dunning Mountain Drum Fire	III
Durham Twp. Sovent Spill	III
E.C. Kramer	IX
Eager Beaver Lumber Co.	III
Eagle Mine	VIII
Earl Allen Chemical Sites	IV
East Bay Site	V
East Cumberland Street	III
East Hanover Site	II

SITE	REGION
Eastern Chemical Co.	IV
Echo Bay Station	IX
Economy Products	VII
Edmond's Salvage Yard	IV
Edwards Road Site	III
Eginore Fertilizer	VII
El Monte Site	IX
Elizabeth City Drum	IV
Elk River - Mitchell Site	X
Elkhart Site	V
Ellerby Refining Site	VIII
Ellis Road	IV
Ellisville Site (Callahan)	VII
Emmitt PCB	X
Englewood DDT	VIII
Envirochem Corp.	V
Environmental Services, Inc.	VII
Erwin Farm	VII
Evans Trail	III
Everhart Lumber Site	IV
Eweing Road Drum Site	III
F/V Victoria II Keehi Lagoon	IX
Fairview Road	I
Farmers Reservoir and Irrigation	VIII
Fennel Road	III
Floating Drum - CG	IX

SITE	REGION
Flood Damage	VII
Floyd Hutter	V
FMHA - USDA / Roy	IV
Forbush Metal Fabricators	IV
Fort & Scotten Streets	V
Fort Anne	II
Fort Drum	II
Fort Totten - CG	II
Franklin/Gimblin St.	VII
Frejonley	VIII
French, Ltd.	VI
Fried Industries	II
Front Street Tanker	III
Ft. Oglethorpe Drum	IV
Fulton Terminals	II
Furnace Road Drum Site	IV
Gail Foster Property	IV
Gallaway Pits	IV
Garage Fire	III
Garden Valley Site	IX
Garfield Street Drum	III
Garner Road Drum	IV
Garvey Avenue Site	IX
Gary Dog Pound	V
Gaston Co. Drum	IV
Gazzola Drive	II

SITE	REGION
Gebhart Fertilizer	V
Geiger (C & M Oil)	IV
Gems Landfill	II
Gene Murren	VIII
General Disposal	IX
General Laminates	IV
Geneva Ind/Furhmann Energy Corp.	IV
George O'Bryan Site	IV
Georgia Highway 138	IV
Gibson Midnight Drum	IV
Gila River Indian Reservation	IX
Gila River Site #2	IX
Gillcrest Road	IV
Gonic Sites	I
Gooken Farms Drum	IV
Goose Farm	II
GP&K, Inc.	V
Gradyville Midnight Dump	III
Graff Drums	VIII
Grand Forks Drum Site	VII
Great Diamond Island	I
Green River Cyanide	VIII
Greenbriar River Flood	III
Greens PCB Drums	VI
Greenspeed Pest & Lawn Management	X
Greenup Tire Fire	IV

SITE	REGION
Greenwood Chemical	III
Greiners Lagoon	V
Gulf Battery Exchange	IV
Hadaway Road	IV
Haddock Airport	VI
Hall Street	I
Hamill - Hooker Road #3	IV
Hampton Cylinders Site	III
Harris Property	III
Harrison Co. PCB Spill	III
Harrison	IV
Harvey & Knott Drum Site	III
Hauulu Beach Park - CG	IX
Hayes Park Pool	II
Head PCB Spill	IV
Heldt Chemical (SD Services)	VIII
Helton Property Site	IV
Heritage / Laurel	VI
Herold Site (Black Hawk)	VIII
High Quality Circuits	VIII
High Quality Plating	III
High Sachem Site	I
High View Terrace	II
Highlands Acid Pit	VI
Hillsborough - Route 206	II
Hipps Road Landfill	IV

SITE	REGION
Hixon Plating	V
Hoffman Drums	VII
Holder Corporation	III
Holley Residence	VI
Hollingsworth Pesticide Site	IV
Hollingsworth Solderless	IV
Holly Street Drum Site	VII
Hollywood Cemetery Site	IV
Horry Co. Fireworks	IV
Horseshoe Road Dump	II
Hougels Neck - CG	I
Housatonic River Drums	I
Houston Ship Channel	VI
Howard Rodger's Drum	III
Hudson River - CG	II
Humpback Mtn. Rd. Drums	IV
Hutchinson Mine Site	III
Hyde Park Drum Site	II
Hytech Chrome	V
I-69	V
Independent Nail	IV
Indiana Refinery	V
Industri-Plex	I
Industrial Avenue (Lowell)	I
Industrial Latex	II
Industrial Plastics	IV

SITE	REGION
Industrial Waste Processing	IX
Ingram Property	IV
Inman Warehouse	IV
International Disc Corp.	V
International Metallurgical Service	II
Interstate 70 Acid Spill	III
Interstate Transformer	III
Iron Hill Road Drum	III
Iron Horse Park	I
Isanti Solvent Sites	V
Ivy Road (Bessie Runner)	IV
J & J Plastics	VI
J & L Drum Site	IV
J. V. Peters	V
J. C. Haynes	V
Jack Dennis Pesticide Burnsite	VI
Jackson St. Drums	VII
Jacques Miller Site (Kirby)	IV
Jagger Lane	II
Jefferson Road Drum	VI
Jimmy's Truck Stop	IV
JMC Plating Co.	IV
John's Refinery	VII
Johns Manville Asbestos Site	I
Johnson Bronze	III
Johnson Property Site	IV

SITE	REGION
K & S Circuits	V
Kabletown Road	III
Kane & Lombard Street Drums	III
Kapinos Site	I
Kearney Drum Dump #1 and #5	II
Kearney Drum Dump #2	II
Keefe Environmental Services	II
Keith Farm Pond	IV
Kennebec (Flood)	I
Kentucky Avenue Well Field	II
Kenyon Street Drum Site	IV
Kershaw Co. Landfill	IV
Keswick Road - CG	I
Kevak Property	III
Keyser Ave. Borehole	III
Keystone Drive Pesticide Dump	III
Kin-Buc Landfill	II
Knapp Creek	III
Krum Trash	III
L. Fricker Co.	IX
Lackawanna Refuse	III
Lacy Manor Drive	VII
Laguna Beach II - CG	IX
Lake Kathy Road Spill	IV
Lake Sandy Jo (M&M Landfill)	V
Lake Sunapee	I

SITE	REGION
Lake Washington Drum - CG	X
Lake Washington Ship Channel - CG	X
Lake Worth Inlet - CG	IV
Lakewood	V
Lakin State Farm	III
Lancaster Battery	III
Lando Drums Site	IV
Landsdowne Radiation Site	III
Landsdowne Site #2	III
LaSalle Electric Utilities	V
Laskin/Poplar Oil Co.	V
Laurel Springs PCB Site	IV
Lee's Lane Landfill	IV
Leetown Pesticide	III
Lehillier/Mankato Site	V
Lemon Lane Landfill	V
Lenoir Refining	IV
Lincoln Avenue	II
Lincoln Avenue / P.J.	II
Linecrest Way	IV
Linemaster Switch Corp.	I
Lipari Landfill	II
Liquid Disposal, Inc.	V
Liquid Dynamics	V
Liquid Waste Management	V
Little League Pesticide	X

SITE	REGION
Lockwood St.	II
Locomotive Junkyard - CG	III
Long Beach Drum - CG	IX
Long Island Beach - CG	II
Lorentz Barrel & Drum	IX
Love Canal (Black Creek)	II
Love Residence	VI
Lowell Road	I
Lowney Way	I
Lubricants, Inc.	V
Lumnis Island - CG	IV
Lusher St. Groundwater	V
Lynnhaven Bay - CG	III
Macon Property	IV
Madison Wire Co.	II
Main Street Well	V
Malitovsky Drum Co.	III
Malleable Range Co.	V
Manilla Creek	III
Marcy Street	VII
Marietta Mercury Spill	IV
Marietta Road	IV
Marrowstone Island - CG	X
Marzone Chemical Co.	IV
Matagorda Island - CG	VI
Matarazzo	I

SITE	REGION
Mathews Electric Plating	III
Mathis Brothers Chickamauga	IV
Mattiace Petrochemicals Company	II
McAllister Drum Site	IV
McColl	IX
McDonald Farm Site	IV
McKinnon	IX
Medley Farm Drum Dump	IV
Mek Spill	II
Mercer County Drum Dump	III
Metcoa Radiation Site	III
Mexico Feed & Seed	VII
Meyers Dump	V
Michael Battery	VII
Michigan City Drums	V
Midco I	V
Middeltown Road Dump	III
Midnight Dump - CG	VI
Midnight Dump	IV
Midnight Dump	I
Midnight Dumping (KY)	IV
Midnight Dumping - Detroit	I
Midnight Dumping/Guilford	IV
Midwest Plating - Kokomo	V
Midwest Plating	V
Mill Creek Dump	III

SITE	REGION
Mill Creek Site (Anaconda)	VIII
Miller Avenue	II
Miller Site	IV
Millpoint (Spring Lake)	V
Minker / Stout / Romaine Creek	VII
Minor Spill / Youngstown - CG	II
Minsei	II
Monon Waterworks	V
Montgomery Ward Store	VIII
Moreland Site	II
Motco, Inc.	VI
Motherlode Facility	VIII
Mottolo Pig Fram	I
Mountain Pine Pressure Treating	VI
Mowbray Engineering Co.	IV
Mt. Elliot Drum	V
Mt. Pocono	III
Mule Creek Drums	VIII
Municipal Landfill	X
Murdock Groundwater	VII
Myers Property	II
N. Lindenhurst	II
N. Tulip St. - Escondido	IX
Nanpasket Beach - CG	I
Nantasket Beach	I
Naomi Drum Site	IV

SITE	REGION
Nascolite Corp.	II
Nashville Pesticide Site	IV
Natchez Drug Site	IV
National Galvanizing	IV
National Vulcanized Fiber	III
Ne.r Wills Point	VI
Neosho Wastewater Treatment School	VII
Nesbit Scale House	IV
New Bedford Site - CG	I
New Castle Containers	III
Newfound Road	IV
Newnan Landfill	IV
Newport Dump	IV
Newsome Brothers/Old Reichold	IV
Niagara Chemical	VI
Nichols Air Strip	IV
Nichro Plating Co.	IV
Nickel Plate Road	III
Nickel Solution Recycling	IX
Niles Township	V
Ninth Avenue Dump	V
Niquette Dr. Asbestos Area 1	I
Niquette Dr. Asbestos Area 2	I
Nodaway Drums	VII
North 'U' Drive PCBs	VII
North Bloomfield	II

SITE	REGION
North-U Drive Well Contamination	VII
Northernaire Plating	V
Northwest Dust Control	X
Northwest Transformer	X
Norwalk Drum Site	IX
Nyanza Chemical	I
O'Con Engineering	IV
O'Sullivan's Island Drum	I
Oak Creek	V
Oakland Junk Yard	III
Oconomowoc Electroplating Inc.	V
Odessa Manufacturing Co.	VII
Ohlson Mountain PCB Site	X
Old American Glycerine-Lewis Run	III
Old Garage	III
Old Henley	VI
Old Inger Oil Refinery	VI
Old Laramore Ltd.	IV
Old Mill	V
Old Springfill Landfill Site	I
Olean Well Field	II
Olympia Pesticide Fire	X
One-Hour Koretizing	IV
Operating Industries	IX
Ordinance Research Institute	IV
Ott/Story/Cordova	V

SITE	REGION
Ottati & Goss/Kingston Steel Drum	I
Pacific Hide & Fur Recycling	X
Padre & Mustang 86 - CG	VI
Padre & Mustang Island IV (Leguna Madre) - CG	VI
Padre & Mustang Islands - CG	VI
Padre & Mustang Islands II - CG	VI
Padre & Mustang Islands III - CG	VI
Pagan Road	III
Pallister Paint Site	X
Palmetto Wood Preserving	IV
Panther Creek - CG	VI
Paoli Rail Yard	III
Paper Steel & Alloys Inc.	IV
Parkside Drive	IX
Parthey Lane	II
Patrick Diehl	III
Payco Pallet & Drum	IV
PBM Enterprises	V
PCB Contaminated Wells	IV
PCB Contamination	X
PCB Midnight Dump	IV
PCB Transformers - CG	IX
PCB Wastes (1-University of Guam)	IX
PCB Wastes (2-University of Guam)	IX
PCB Wastes (3-Guam Memorial Hospital)	IX
PCB Wastes (4-Guam Public Hospital)	IX

SITE	REGION
PCB Wastes (5-Guam Department of Agriculture)	IX
PCB Wastes (7-Guam Department of Economics)	IX
PCB Wastes (8-Guam Phys.)	IX
PCB Wastes (9-Guam PHL)	IX
PCB Wastes (11-Harmon)	IX
PCB Wastes (13-GPA/Naval Station)	IX
PCB Wastes (14-CNMI PCB)	IX
PCB Wastes (15-Saipan)	IX
PCB Wastes (16-Palau)	IX
PCB Wastes (17-Marshall Island)	IX
PCB Wastes (18-Guam Department of Public Health)	IX
PCB Wastes (19-Marshall Island)	IX
PCB Wastes (20-Marshall Island)	IX
PCB Wastes (21-Ebeye Pub)	IX
PCB Wastes (25-Ponape Elect)	IX
PCB Wastes (26-Ponape)	IX
PCB Wastes (27-Ponape DPFOR)	IX
PCB Wastes (28-Ponape)	IX
PCB Wastes (29-Kosrae)	IX
PCB Wastes (30-Truk)	IX
PCB Wastes (32-Yap)	IX
PCB Wastes (33-Yap)	IX
PCB Wastes (A-Guam Department of Education)	IX
PCB Wastes (B-Dela Cruz)	IX
PCB Wastes (C-Majuro Hospital)	IX
PCB Wastes (D-Medical Clinic)	IX

SITE	REGION
PCB Wastes (F-Prot Yap)	IX
PCB Wastes (G-USCG Loran)	IX
PDC Spas	VIII
Peachtree Mercury Spill	IV
Peerless Plating	V
Pembroke Pines	IV
Pepper Steel & Alloys, Inc.	IV
Perona Tire Fire	II
Persons Property PCB Drums	IV
Pesses Chemical	VI
Petersburg Flood	III
Petro Chemical	IV
Petro-Chemical Systems	VI
Petroleum Power & Maintenance	V
Petroleum Products (Pembroke Road)	IV
Picillo Farm	I
Pier 35 - CG	IX
Pine Street Canal	I
Pinette's Salvage Yard	I
Piney Creek Drum	III
Pioneer Sand Co.	IV
Pirates Beach - CG	VI
Plastifax, Inc.	IV
Plating Equipment Used	V
Plymouth Wood Treatment	IV
Poer Farm	V

SITE	REGION
Pointer Asbestos	I
Pollution Abatement Services (PAS)	II
Poly-Carb	IX
Pomona Oaks Residential Wells	II
Portage Drums	V
Potters Pits	IV
Pottstown Abandoned Trailer	III
Precious Metals Inc.	III
Primo Shield	II
Printed Circuits, Inc.	III
Pronto Services	VI
Puerto Rico Organic Inc.	II
Pulverizing Plant Drum Site	IV
Pulverizing Services	II
Purity Oil Sales, Inc.	IX
Quail Run Mobile Manor	VII
Quanta Resources	II
Queens Property	IV
R.J. Trucking	V
Randall Residence	VIII
Raser Tannery	V
Rasmussen's Dump	V
Ray York Body Shop	III
Reimer Drum	IV
Reliable Plating Co.	V
Reliance Refining Co.	VIII

SITE	REGION
Renora, Inc.	II
Reuping Leather Co.	V
Revere Chemical Co.	III
Revere Copper & Brass	V
Rhinehart Tire Fire Dump	III
Richardson Property	II
Richmond St. Drum	VIII
Ridge Ave. Asbestos	I
Ridgeview PCB Site	III
Rigel Street Site	IX
Riverside Cemetery Drums	VIII
Roanoke River Drums	III
Robert Street Drums	VII
Rock Bridge Park	IV
Rock Road Drum Spill	IV
Rockwood School District	VII
Rocky Mountain Custom Chrome	VIII
Rodgers Laboratories	V
Roe Lane Tank	VII
ROIC - Sun Valley	IX
Rolfite Canal Street	I
Rome Coal Tar	IV
Roosevelt Highway Spill	IV
Rose Chemical	VII
Rose Township Dump	V
Rotunda Drive	III

SITE	REGION
Route 13 Drum Site	III
Route 211 Pesticide Site	IV
Route 563 Drum Site	III
Rowes Corner Drum Dump	IV
Rumple Junkyard	V
Rusha Farm	VII
Russell Avenue Asbestos Area	I
Ryan Paints	IX
Rye Street Pesticide	I
S. Bank Asbestos	I
S. Electroforming	IV
S. Valley PCB Tank Site	VI
S.E.R. Plating	V
Saco Tannery Pits	I
Sacramento River - CG	IX
Sag Harbor	II
Saginaw Painting Co.	V
Salem Acres	I
Salvage Oil of America	IV
Salvo Property	IV
Sammis Avenue - Deer Park	II
Samoset Avenue Chemical Spill	I
Sampson County Dumpster	IV
Sand Key - CG	IV
Sand, Gravel & Stone	III
Sandonelle PCB	III

SITE	REGION
Sanford Plating Company	IV
Sasser Electric Co. Drum	III
Satala Power Plant I	X
Satellite/Ammet Incendiary	III
Savage Municipal Water Supply	I
Schmalz Dump	V
Scotts Creek Battery	IV
Sealand, Ltd.	III
Seaway Warehouse	V
Security Boulevard	III
Selkirk - Benham St.	V
Semco PCB Site	III
Senuta Residence	VI
Seymour Recycling Corp.	V
Shady Lane Asbestos	I
Shaffer Equipment Co.	III
Shelton Wells	V
Ship Channel - CG	VI
Shirley #2	II
Signo Delta Warehouse	II
Signo Trading / Mount Vernon	II
Signo Trading	II
Signo/Coty	II
Signo/Kenston	II
Sikes Disposal Pits	VI
Silresim Chemical Corp.	I

SITE	REGION
Silver Bow Creek / Walkerville	VIII
Silverado Leach Mill	IX
Simpson Road Drum	IV
Skiljan/Dial	V
Skylark (Yates Residence)	VI
Smith's Farm	IV
Snapper Lane - CG	IV
Solid State Circuits	VII
Solly Avenue Midnight Dump	III
Sonford Products	IV
Sorrento Site	V
South Acres	VI
South Adams County Water District	VIII
South Bay Asbestos Area	IX
South Half Moon Bay - CG	IX
South of Waco	VI
South Riverdale Drive	IV
South Valley / Whitfield	VI
Southern Lumber Co.	IV
Southern Maryland Wood Treating	III
Spectro Chemical Co.	V
Spokane Drum Fire	X
Springer Septic Services - CG	III
SSCD Schoolyard Site	III
St. John River - CG	IV
St. Louis River - CG	V

SITE	REGION
Stamina Mills, Inc.	I
Standard Chemical Co.	IX
Stanford Site #1	IX
Stanford Site #2	IX
Starbrick	III
Steel Container	V
Stevenson Road Drum	V
Stewart Drum	V
Stewco, Inc.	VI
Stoneman Property	III
Store Safe Explosives	VII
Stringfellow Acid Pits	IX
Styrene Spill - CG	VI
Sullins Residence	VII
Summit Equipment & Supplies	V
Summit National	V
Sunset Golf Course	III
Swainsboro Print Works	IV
Sweetwater Creek Drums	IV
Swissvale Auto	III
Sycamore Street	V
Sylvester	I
T.P. Long	V
Tafuna Power Plant	IX
Talley Farm	VII
Taputimu Farm	IX

SITE	REGION
Tar Creek (Ottawa County)	VI
Taylor Borough Dump	III
Taylorsport Sand & Gravel	IV
Tecate Site	IX
Texarkana Woodpreserving	VI
The Chrome Shop	IX
Tholozan Street Site	VII
Thorn Run Spill	II
Tidewater TNT	III
Tindall Property Transformer	IV
Tinicum Marsh	III
Tinkham Garage	I
Tower Chemical Co.	IV
Town of Kent	II
Town of Pompey	II
Trans Tech / Adamstown	III
Tri-City Oil Conservationist, Inc.	IV
Tri-State Engineering	III
Triangle Chemical Co.	VI
Trowbridge Estates Mercury	III
Truck Accident	VIII
Try Chem Corp.	V
Tuba City Acid Tank	IX
Turco Coatings	III
Turkey Creek Barrel Dump	IV
Tybouts Corner Landfill	III

SITE	REGION
Tyler Street Drums	V
Tysons Dump	III
U.S. 70 Dump Site	IV
U.S. Customs Pesticide	IV
U.S. DOT - Standard Steel	X
Union Ave. - PCB Site	X
Union Chemical Co.	I
Union Co. Drum	IV
Union Plating	III
Union Scrap Iron and Metal Co.	V
United Chrome Products Inc.	X
United Rigging & Hauling	II
United Scrap Lead Co.	V
Unknown Chemical Discharge - CG	IV
Unknown Chemical Drums - CG	IX
Upper Glade Drum	III
Upshur County 4-H Tarpit	III
US Highway 1 Truck Site	IV
US Scrap	V
Vaagen-Dahle Farm	VIII
Valley Garden Drive	VII
Valleywood Subdivision	V
Verona Well Field	V
Villa Rich - High Point Rd.	IV
Vulcanized Rubber & Plastics	III
W. 58th Street Drum Site	V

SITE	REGION
W.J. Oil Co.	VI
Wach's Landfill	III
Wade (ABM)	III
Wade Park Chemicals	V
Wading River	II
Waldick Aerospace Devices	II
Walkerton Tire Fire	III
Wallkill Well	II
Walter Taylor	III
Wasatch Chemical Co. (Lot 6)	VIII
Washoe Drum	IX
Waste Disposal Inc.	IX
Wausau Groundwater Contamination	V
Weaver Drums	VII
Wedzeb Enterprises Inc.	V
Western Carolina Smelting	IV
Western Processing Co., Inc.	X
Western Sand & Gravel	I
Western States Refining	IX
Westinghouse Elevator Co.	III
Westline Site	III
Westville Oil (Cam - Or)	V
Wheatland Drum	VI
Wheeling Acid Spill	III
Wheeling Hill	III
Whitehouse Oil Pits	IV

SITE	REGION
Whitemarsh Twp. Drum	III
Whitley County	IV
Whittier Propel	IX
Wide Beach Development	II
Williamette River - CG	X
Williams & Son	X
Williams Pesticide Site	IV
Windus Drive	II
Winkler Road	VI
Woodbury Chemical Co.	VIII
Woodward Mill Road	IV
Woodward Property Drums	IV
Woody's Tire Fire	IV
Worthington Spring Site	IV
Yellow Water Road Drum	IV
Yokum Chlordane Contamination	III
York Oil Company	II
Yucaipa Drug Lab	IX
Zenith Chemical	IV

U.S. GOVERNMENT PRINTING OFFICE: 1989-648-163/00304